





report date: 2024-03-29

### General information

Make	AUDI
Model	A8 TDI QUATTRO DPF SPORT
Colour	Blue
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	5.9 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	326 BHP
Max. torque	650 Nm at 1.600 rpm
Engine capacity	4.172 cc
Cylinders	8
Fuel type	Diesel
Consumption city	20.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	258 g/km
CO2 label	M



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-12-06

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history
-------------

MOT expiry date	2025-04-08
MOT pass rate	100 %
MOT passed	17
Failed MOT tests	0
Total advice items	22
Total items failed	0

MOT #17	2024-04-09 10:03
MOT test number	717986582654
Result	<b>✓</b> Passed
Next expiry date	2025-04-08
Minor Nearside Rear Stop lamp(s) lens defective which has no effect o	n emitted light (4.3.1 (b) (i))

MOT #16	2023-05-02 10:40
MOT test number	196094181256
Result	<b>✓</b> Passed
MOT #15	2022-05-28 08:43
MOT test number	990851603399
Result	<b>✓</b> Passed
MOT #14	2021-12-02 16:45
MOT test number	343816414644
Result	✓ Passed

CarCheck.co.uk page 3/13



**MOT #13** 2021-01-18 14:25

MOT test number 667282042474

Result \rightarrow Passed

**Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement all 4 top arm bushes splitting (5.3.4 (a) (i))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #12** 2020-01-14 09:12

MOT test number 186829083614

**Result** ✓ Passed

**Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement all 4 top arms inner bushes starting to split (5.3.4 (a) (i))

**MOT #11** 2019-01-14 09:53

MOT test number 363576710725

Result 

Passed

**Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both front both top arms inner bushes (5.3.4 (a) (i))

**MOT #10** 2018-01-15 14:38

MOT test number 700857845088

Result 

Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

CarCheck.co.uk page 4/13



MOT #9 2017-01-17 10:15

**MOT test number** 237444989787

**Result** ✓ Passed

**Advice** Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive

movement both (2.4.G.2)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2016-01-28 14:34

**MOT test number** 386119005012

Result \rightarrow Passed

Advice Front brake discs lipped/corroded

**Advice** Front top (rear suspension arm) bush split

Advice Rear brake discs lipped and corroded, pads approx. 85-90%worn

**MOT #7** 2014-10-29 10:09

**MOT test number** 187802004301

Result \square Passed

MOT #6 2013-10-31 11:00

**MOT test number** 956844403308

MOT #5 2012-11-09 14:13

**MOT test number** 329844512367

CarCheck.co.uk page 5/13



MOT #4 2011-11-03 12:23

**MOT test number** 366917301385

Result \rightarrow Passed

Advice

Offside Front Upper Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #3 2010-11-25 15:16

MOT test number 481939320483

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2010-01-22 10:56

MOT test number 842972320003

Result 

Passed

Advice Nearside Front Lower Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #1** 2009-01-23 11:49

**MOT test number** 184863329464

**Result** ✓ Passed

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this AUDI? How many owners did check it in the premium report and see all owner registrations. Download the full report is	
********	
***************************************	
************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SAIN
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-03-01
Last registration	2024-04-09
Complete history	See info



Registration #1	2006-03-01	19 mi
Registration #2	2009-01-23	35.797 mi
Registration #3	2010-01-22	44.818 mi
Registration #4	2010-11-25	51.199 mi
Registration #5	2011-11-03	57.356 mi
Registration #6	2012-11-09	64.582 mi
Registration #7	2013-10-31	34.772 mi
Registration #8	2014-10-29	75.580 mi
Registration #9	2016-01-28	80.502 mi
Registration #10	2017-01-17	83.609 mi
Registration #11		11.177 mi
Registration #12		11.117 es
Registration #13		
Registration #14		11.777 es
Registration #14 Registration #15		11.777 es
_		11.777 es 11.777 es
Registration #15		11.777-00 11.777-00 11.777-00
Registration #15 Registration #16		11.777-00 11.777-00 11.777-00 11.777-00

More info >

CarCheck.co.uk page 12/13



### Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1894 mm
Height	1444 mm
Length	5062 mm
Wheel base	2944 mm
Kerb weight	1945 kg
Max. allowed weight	2545 kg

### Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	BVN 003458

CarCheck.co.uk page 13/13