



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Grey
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 2


Date	2021-07-20
Pictures	2
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-05-24
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-28
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	34
Total items failed	10

MOT #16	2023-07-21 13:46
MOT test number	428331337237
Result	✓ Passed
Next expiry date	2024-07-28
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15	2023-07-21 08:20
MOT test number	934092286317
Result	✗ Failed
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #14**

2022-07-21 15:54

MOT test number

301247888557

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13**

2021-07-29 15:10

MOT test number

851512075675

Result

✓ Passed

Advice Both rear shock absorber dust cover detached**MOT #12**

2021-07-28 14:38

MOT test number

616042340882

Result

✗ Failed

Advice Both rear shock absorber dust cover detached**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11**

2020-11-16 12:43

MOT test number

671338882325

Result

✓ Passed

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10**

2019-05-09 08:06

MOT test number

428769737667

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2019-05-08 08:14

MOT test number

446018172894

Result

✗ Failed

Advice Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Direction indicator not working wing/mirror indicator (4.4.1 (a) (ii))**MOT #8**

2018-03-19 16:08

MOT test number

668056597170

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)**Advice** Windscreen badly cracked out side of swept area

**MOT #7** 2018-03-19 10:28**MOT test number** 479128602191**Result** ✗ Failed**Advice** Offside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)**Advice** Windscreen badly cracked out side of sweated area**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #6** 2017-03-24 13:49**MOT test number** 974329282749**Result** ✓ Passed**Advice** Front windscreen is damaged**Advice** Front registration plate deteriorated but not likely to be misread number plate is cracked (6.3.1d)**Advice** Covers impede parts of the inspection**Advice** Both sides front brake pads worn thin - just meets the pass standard today**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2017-03-22 12:22**MOT test number** 915900425748**Result** ✗ Failed**Advice** Both sides front brake pads worn thin - just meets the pass standard today**Advice** Front registration plate deteriorated but not likely to be misread number plate is cracked (6.3.1d)**Advice** Front windscreen is damaged**Fail** Nearside Front Headlamp aim beam image obviously incorrect non defined beam pattern (1.8.A.1b)**Advice** Covers impede parts of the inspection



MOT #4 2015-03-23 14:18

MOT test number 348932085017

Result ✓ Passed

MOT #3 2015-03-20 13:35

MOT test number 436079675001

Result ✗ Failed

Fail Nearside Headlamp aim too high (1.8)

Fail Nearside Headlamp insecure (1.7.3)

MOT #2 2013-03-20 09:39

MOT test number 937829273095

Result ✓ Passed

MOT #1 2012-03-27 09:51

MOT test number 435337482061

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
28 July 2024

Tax status		Valid until 1 September
Days left		124
MOT expiry date		28 July 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GY09FCJ
Plate since	2019-06-29
Current registration	 GY09FCJ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-31
Last registration	2023-07-21
Complete history	See info



Registration #1	2009-03-31	15 mi
Registration #2	2012-03-27	18.045 mi
Registration #3	2013-03-20	25.705 mi
Registration #4	2015-03-20	38.649 mi
Registration #5	2015-03-23	38.650 mi
Registration #6	2017-03-22	59.055 mi
Registration #7	2017-03-24	59.090 mi
Registration #8	2018-03-19	68.734 mi
Registration #9	2018-03-19	68.734 mi
Registration #10	2019-05-08	78.610 mi
Registration #11	2019-05-08	78.610 mi
Registration #12	2019-05-08	78.610 mi
Registration #13	2019-05-08	78.610 mi
Registration #14	2019-05-08	78.610 mi
Registration #15	2019-05-08	78.610 mi
Registration #16	2019-05-08	78.610 mi
Registration #17	2019-05-08	78.610 mi
Registration #18	2019-05-08	78.610 mi
Registration #19	2019-05-08	78.610 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BUD579339