



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI BLUEMOTION
Colour	Red
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption



Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1	
Date	2021-06-15
Pictures	51
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-05-16
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	28
Total items failed	0

**MOT #15** 2023-04-27 14:55**MOT test number** 419034221875**Result** ✓ Passed**Next expiry date** 2024-05-16**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front wishbone rear bushes. (5.3.4 (a) (i))**MOT #14** 2023-04-24 09:30**MOT test number** 305865445567**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front wishbone rear bushes. (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Nearside Front Side repeater not working (4.4.1 (a) (ii))

**MOT #13** 2022-05-17 14:10**MOT test number** 108685244916**Result** ✓ Passed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #12** 2022-05-12 11:47**MOT test number** 910732784638**Result** ✗ Failed**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11** 2021-05-08 12:17**MOT test number** 157333363707**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2020-05-11 11:20**MOT test number** 444466250070**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9** 2020-05-11 08:30**MOT test number** 762475243462**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Front Anti-roll bar linkage ball joint excessively worn both (5.3.4 (a) (i))**MOT #8** 2019-06-07 09:00**MOT test number** 193848590203**Result** ✓ Passed**MOT #7** 2018-06-18 16:25**MOT test number** 655112752334**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2018-06-18 08:18**MOT test number** 980313404437**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt both sides (5.3.4 (b) (ii))**MOT #5** 2017-06-16 08:15**MOT test number** 492872351489**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt



<b>MOT #4</b>	2016-06-24 08:14
---------------	------------------

<b>MOT test number</b>	376989774772
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Shock absorber has a light misting of oil (2.7.3)
---------------	---

<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

<b>MOT #3</b>	2015-07-03 09:16
---------------	------------------

<b>MOT test number</b>	746744685142
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-07-19 09:41
---------------	------------------

<b>MOT test number</b>	347180404249
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2013-06-14 15:14
---------------	------------------

<b>MOT test number</b>	218465263454
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
16 May 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	16 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>DA10ZLE</b>
Plate since	2019-03-29
Current registration	 <b>DA10ZLE</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-07
Last registration	2023-04-27
Complete history	<a href="#">See info</a>



Registration #1	2010-07-07	7 mi
Registration #2	2013-06-14	59.606 mi
Registration #3	2014-07-19	62.671 mi
Registration #4	2015-07-03	69.033 mi
Registration #5	2016-06-24	76.154 mi
Registration #6	2017-06-16	81.699 mi
Registration #7	2018-06-18	86.869 mi
Registration #8	2018-06-18	86.869 mi
Registration #9	2019-06-07	90.378 mi
Registration #10	2019-06-07	90.378 mi
Registration #11	2019-06-07	90.378 mi
Registration #12	2019-06-07	90.378 mi
Registration #13	2019-06-07	90.378 mi
Registration #14	2019-06-07	90.378 mi
Registration #15	2019-06-07	90.378 mi
Registration #16	2019-06-07	90.378 mi
Registration #17	2019-06-07	90.378 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1781 mm
Height	1504 mm
Length	4534 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAY 080363