




report date: 2024-05-25

General information

Make	MINI
Model	COUNTRYMAN COOPER S ALL4A COOPER S ALL4
Colour	Grey
Year of manufacture	2012
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history


Entry 4

Date	2023-12-05
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 3

Date	2023-11-17
Pictures	17
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2

Date	2023-08-21
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-05-30
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #13 2024-05-31 10:20

MOT test number 180413447132

Result ✓ Passed

Next expiry date 2025-05-30

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12 2023-07-03 13:50

MOT test number 122401751841

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #11 2022-07-01 07:27

MOT test number 369971020061

Result ✓ Passed

Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))



MOT #10 2022-06-20 14:26

MOT test number 631045898020

Result ✗ Failed

Advice Offside Front Inner Play in steering rack inner joint(s)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Front Inner Play in steering rack inner joint(s)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))

MOT #9 2021-06-21 17:04

MOT test number 234004890338

Result ✓ Passed

MOT #8 2020-09-21 10:53

MOT test number 683449549037

Result ✓ Passed

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

Advice Nearside Front Nail in tyre

MOT #7 2019-09-19 12:00

MOT test number 309006601414

Result ✓ Passed



MOT #6	2018-08-15 09:00
MOT test number	546445945183
Result	✓ Passed
Advice	Offside Front Nail in tyre
Minor	Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

MOT #5	2018-06-07 08:55
MOT test number	96077285252
Result	✓ Passed

MOT #4	2017-12-06 12:25
MOT test number	688549941107
Result	✓ Passed

MOT #3	2016-11-30 14:29
MOT test number	152615837356
Result	✓ Passed
Advice	Offside Front Tyre worn on inner and outer edges
Advice	Nearside Front Tyre wearing on inner and outer edges

MOT #2	2015-12-02 15:32
MOT test number	155915078865
Result	✓ Passed

MOT #1	2014-12-16 14:56
MOT test number	947910254344
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 December 2024

✓
MOT

Expires:
30 May 2025

Tax status Valid until 1 December

Days left 162

MOT expiry date 30 May 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YX11
Plate since	2019-05-25
Current registration	YX11
Plate since	2019-05-25

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-09-21
Last registration	2024-05-31
Complete history	See info



Registration #1	2012-09-21	16 mi
Registration #2	2014-12-16	30.851 mi
Registration #3	2015-12-02	39.501 mi
Registration #4	2016-11-30	47.983 mi
Registration #5	2017-12-06	56.125 mi
Registration #6	2018-06-07	60.049 mi
Registration #7	2018-08-15	60.076 mi
Registration #8	2019-09-19	76.293 mi
Registration #9	2020-09-21	75.971 mi
Registration #10	2020-09-21	75.971 mi
Registration #11	2020-09-21	75.971 mi
Registration #12	2020-09-21	75.971 mi
Registration #13	2020-09-21	75.971 mi
Registration #14	2020-09-21	75.971 mi
Registration #15	2020-09-21	75.971 mi
Registration #16	2020-09-21	75.971 mi
Registration #17	2020-09-21	75.971 mi
Registration #18	2020-09-21	75.971 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1405 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

