





report date: 2024-03-29

General information

Make	MAZDA
Model	5 D SPORT NAV
Colour	Red
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/10



report date: 2024-03-29

2021-11-11 16:44

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT #11

MOT expiry date	2023-11-25
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #12	2022-11-26 13:09
MOT test number	151854104029
Result	✓ Passed
Next expiry date	2023-11-25

MOT test number	177143569566
Result	✓ Passed
Advice Nearside Rear Suspension arm pin or bush worn but not resulting i bush deteriorated (5.3.4 (a) (i))	in excessive movement forward

MOT #10	2020-10-08 08:36
MOT test number	257641742040
Result	✓ Passed

MOT #9		2019-04-12 10:48
MOT test	number	698768783099
Result		✓ Passed
Advice	Both inner sills have slight corrosion	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Rear suspension starting to get rusty	

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT #8 2018-04-11 10:50

MOT test number 111663578866

Result ✓ Passed

MOT #7 2017-04-13 08:18

MOT test number 176840961600

Result

Passed

Advice Rear Tyre worn close to the legal limit both wearing unevenly on inner edge (4.1.E.1)

MOT #6 2016-04-18 08:37

MOT test number 541549192868

Result
✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Offside Front tyre worn inner edge

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive

movement rear bush (2.4.G.2)

Advice Nearside Front tyre wearing inner edge

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2015-04-23 17:50

MOT test number 728243115191

Result

Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

Rear discs corroded on inner surfaces

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

(2.4.G.2)

Notice

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #4 2014-04-24 16:02

MOT test number 275524114436

Result \(\sqrt{Passed} \)

Notice Corrosion on rear discs and pads not making full contact on discs (brake efficiency ok)

Notice Rear fog light loose in bumper housing.

MOT #3 2013-04-25 16:07

MOT test number 617815113180

Result ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2013-04-25 16:07

MOT test number 886775713174

Result X Failed

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Offside Headlamp aim too high (1.8)

MOT #1 2012-05-17 11:55

MOT test number 599518632178

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owi		bio.	+	,
U) W)	121	mis		//

,		
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		A

	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-05-22
Last registration	2022-11-26
Complete history	See info



Registration #1	2009-05-22	12 mi
Registration #2	2012-05-17	21.621 mi
Registration #3	2013-04-25	28.416 mi
Registration #4	2014-04-24	37.458 mi
Registration #5	2015-04-23	42.681 mi
Registration #6	2016-04-18	47.145 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1535 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	RF 10246627

CarCheck.co.uk page 10/10