



ND60FYW

report date: 2024-03-29

General information

| | |
|---------------------|--------------------|
| Make | FORD |
| Model | TRANSIT 280 LR P/V |
| Colour | White |
| Year of manufacture | 2010 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-----------------|---------------------|
| Power | 85 BHP |
| Max. torque | 250 Nm at 2.200 rpm |
| Engine capacity | 2.198 cc |
| Cylinders | 4 |
| Fuel type | Diesel |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-07 |
| Pictures | 3 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-11-04 |
| MOT pass rate | 59 % |
| MOT passed | 10 |
| Failed MOT tests | 7 |
| Total advice items | 33 |
| Total items failed | 39 |

MOT #172022-11-05 12:38

MOT test number429954757424

Result✓ Passed

Next expiry date2023-11-04

- Minor

Nearside Obligatory mirror slightly damaged door mirror (3.3 (b) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Oil leak, but not excessive power steering pipe (8.4.1 (a) (i))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #16**

2022-11-03 17:03

MOT test number

295980883990

Result**✗ Failed****Advice**

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor

Nearside Obligatory mirror slightly damaged door mirror (3.3 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Fail

Nearside Front Inner Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected (5.3.6 (a) (ii))

Fail

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail

Windscreen washer not working (3.5 (a))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Oil leak, but not excessive power steering pipe (8.4.1 (a) (i))

Fail

Offside Front Inner Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected (5.3.6 (a) (ii))

MOT #15

2021-10-28 15:54

MOT test number

419057276829

Result**✓ Passed**

**MOT #14**

2021-10-21 15:16

MOT test number

332231763220

Result**✗ Failed**

- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Brake pipe likely to become detached or damaged (1.1.11 (d) (ii))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Battery light on

MOT #13

2020-10-28 11:19

MOT test number

696710015931

Result**✓ Passed**

- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-10-25 14:24**MOT test number** 595119514455**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Suspension rod ball joint has slight play (5.3.4 (a) (i))**Advice** Front wipers don't park correctly**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2018-10-26 14:04**MOT test number** 913366869991**Result** ✓ Passed**MOT #10** 2018-10-26 09:06**MOT test number** 943971882805**Result** ✗ Failed**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Fail** Offside Front Suspension rod ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Fail** Offside Front Suspension arm pin or bush likely to become detached rear bush (5.3.4 (a) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2017-10-27 12:10**MOT test number** 141617095930**Result** ✓ Passed**MOT #8** 2017-10-27 11:11**MOT test number** 295482592040**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #7** 2016-10-28 13:49**MOT test number** 499344991501**Result** ✓ Passed**MOT #6** 2016-10-28 08:43**MOT test number** 826656886564**Result** ✗ Failed**Advice** High level stop lamp inop**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)

**MOT #5** 2015-10-07 12:24**MOT test number** 574889831588**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #4** 2015-10-07 09:19**MOT test number** 242680353081**Result** ✗ Failed**Fail** Front registration plate deteriorated (6.3.1d)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #3** 2014-11-03 14:45**MOT test number** 425777404396**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2014-11-03 10:44**MOT test number** 928417604386**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



| | |
|-----------------|------------------|
| MOT #1 | 2013-11-21 09:55 |
| MOT test number | 689855723368 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✗
MOT
Expired:
4 November 2023

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 4 November 2023 |
| Full MOT history | See MOT history |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2024-03-29 |
| Current registration | ***** |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2010-12-14 |
| Last registration | 2022-11-05 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-12-14 | 24 mi |
| Registration #2 | 2013-11-21 | 45.903 mi |
| Registration #3 | 2014-11-03 | 56.923 mi |
| Registration #4 | 2014-11-03 | 56.923 mi |
| Registration #5 | 2015-10-07 | 71.211 mi |
| Registration #6 | 2015-10-07 | 71.211 mi |
| Registration #7 | 2016-10-28 | 80.978 mi |
| Registration #8 | 2016-10-28 | 80.978 mi |
| Registration #9 | 2017-10-27 | 89.615 mi |
| Registration #10 | 2017-10-27 | 89.616 mi |
| Registration #11 | 2019-05-29 | 95.377 mi |
| Registration #12 | 2019-05-29 | 95.377 mi |
| Registration #13 | 2019-05-29 | 95.377 mi |
| Registration #14 | 2019-05-29 | 95.377 mi |
| Registration #15 | 2019-05-29 | 95.377 mi |
| Registration #16 | 2019-05-29 | 95.377 mi |
| Registration #17 | 2019-05-29 | 95.377 mi |
| Registration #18 | 2019-05-29 | 95.377 mi |
| Registration #19 | 2019-05-29 | 95.377 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1974 mm |
| Height | 1989 mm |
| Length | 4863 mm |
| Wheel base | 2933 mm |
| Kerb weight | 1699 kg |
| Max. allowed weight | 2800 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 80 l |
| Fuel delivery | Direct Injection |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | AA86453 |