



report date: 2024-03-28

## General information

Make	VOLVO
Model	V40 D2 CROSS COUNTRY LUX
Colour	Black
Year of manufacture	2016
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	118 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-05-05
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #7	2024-04-20 11:00
MOT test number	588730529986
Result	✓ Passed
Next expiry date	2025-05-05
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6	2023-04-27 14:55
MOT test number	918804417983
Result	✓ Passed
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2023-04-27 08:11**MOT test number** 103297843430**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2022-04-27 11:46**MOT test number** 355470758501**Result** ✓ Passed**MOT #3** 2021-05-06 07:42**MOT test number** 438003775793**Result** ✓ Passed**MOT #2** 2020-03-06 10:45**MOT test number** 619749943077**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2019-02-27 10:38**MOT test number** 170897705284**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
5 May 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	5 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>RX16SXO</b>
Plate since	2019-09-29
Current registration	<b>RX16SXO</b>
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-09
Last registration	2024-04-20
Complete history	<a href="#">See info</a>



Registration #1	2016-03-09	22 mi
Registration #2	2019-02-27	33.818 mi
Registration #3	2020-03-06	48.499 mi
Registration #4		
Registration #5	2021-05-06	49.032 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1470 mm
Length	4370 mm
Wheel base	2646 mm
Kerb weight	1510 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1264673