





General information

| Make | KIA |
|---------------------|----------------|
| Model | PICANTO SR7 |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 98 mph |
| 0 - 60 mph | 14.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 65 BHP |
|-------------------------|--------------------|
| Max. torque | 95 Nm at 3.500 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 105 g/km |
| CO2 label | В |







Internet history

| E | n | t | y | 1 |
|---|---|---|---|---|
| | | | | |

Date

Pictures

2021-02-01

9

Listing price

View report



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-01-30 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 3 |

| MOT #7 | 2024-01-02 12:05 |
|--|------------------|
| MOT test number | 141410439441 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-30 |
| Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice Vehicles internal headlight adjuster altered to recheck lights | |
| Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) | |

| MOT #6 | 2023-01-31 12:12 |
|--|------------------|
| MOT test number | 974140056523 |
| Result | ✓ Passed |
| Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) | |





| MOT #5 | | 2023-01-30 15:13 |
|---------------------------|---|------------------|
| MOT test number | | 158474244861 |
| Result | | × Failed |
| Pass with rectification | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Fail Offside Front Tyre t | read depth below requirements of 1.6mm (5.2.3 (e)) | |
| Minor Battery insecure | but not likely to fall from carrier (4.13 (a) (i)) | |
| Fail Nearside Front Tyre | e has ply or cords exposed (5.2.3 (d) (ii)) | |
| | | |
| MOT #4 | | 2022-01-08 10.53 |

| MOI #4 | 2022-01-08 10:53 |
|-----------------|------------------|
| MOT test number | 215247860362 |
| Result | ✓ Passed |
| | |

| MOT #3 | 2021-01-08 16:51 |
|-----------------|------------------|
| MOT test number | 891924144509 |
| Result | ✓ Passed |
| | |

| 753734676413 |
|--------------|
| ✓ Passed |
| |

| MOT #1 | 2019-01-19 11:24 |
|-----------------|------------------|
| MOT test number | 675857884460 |
| Result | ✓ Passed |



Tax & MOT check

| Tax due: 1 March 2025 | ✓ Taxed | Expires: 30 January 2025 | ✓ МОТ |
|---------------------------------|------------|------------------------------------|---------------------|
| Tax status | | | Valid until 1 March |
| Days left | | | 305 |
| MOT expiry date | | | 30 January 2025 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|--|-------|
| Date | | |
| Category | | ARMP |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | AT I |
| Date | | * |
| Category | AMA | |
| Туре | No. Contraction of the second se | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plata since | |
| | |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2016-01-23 |
| Last registration | 2024-01-02 |
| Complete history | See info |



| Registration #1 | 2016-01-23 | 15 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-01-19 | 30.170 mi |
| Registration #3 | 2020-01-18 | 38.513 mi |
| Registration #4 | 2021-01-08 | 44.891 mi |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.117 est |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.117 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 83% |
| Pedestrian | 47% |
| Safety systems | 43% |
| Overall rating | 73% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1595 mm |
| Height | 1480 mm |
| Length | 3595 mm |
| Wheel base | 2385 mm |
| Kerb weight | 1039 kg |
| Max. allowed weight | 1400 kg |
| Additional information | |
| Fuel tank capacity | 35 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G3LAFP113769 |