



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER
Colour	Black
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-06-09
Pictures	34
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #12	2023-06-23 10:52
MOT test number	541876235113
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Front Oil leak, but not excessive gearbox (8.4.1 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #11** 2023-06-23 08:20**MOT test number** 646388772384**Result** ✗ Failed**Fail** Front Headlamp aim too high both side (4.1.2 (a))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2022-07-01 08:37**MOT test number** 166391804444**Result** ✓ Passed**MOT #9** 2021-10-19 10:25**MOT test number** 792617788801**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both side (1.1.14 (a) (ii))**MOT #8** 2020-10-14 11:55**MOT test number** 317840612932**Result** ✓ Passed**MOT #7** 2019-10-15 09:13**MOT test number** 130801510898**Result** ✓ Passed

**MOT #6** 2018-10-09 13:44**MOT test number** 451704230169**Result** ✓ Passed**MOT #5** 2018-10-09 11:45**MOT test number** 635800676636**Result** ✗ Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #4** 2017-10-12 11:57**MOT test number** 932423331093**Result** ✓ Passed**MOT #3** 2016-10-12 13:32**MOT test number** 600336519627**Result** ✓ Passed**MOT #2** 2015-10-15 15:04**MOT test number** 794444855619**Result** ✓ Passed**MOT #1** 2014-12-16 12:27**MOT test number** 517740754347**Result** ✓ Passed

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
30 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	30 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	EA61HZX
Plate since	2019-09-28
Current registration	EA61HZX
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-10-22
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2011-10-22	9 mi
Registration #2	2014-12-16	23.535 mi
Registration #3	2015-10-15	29.148 mi
Registration #4	2016-10-12	36.932 mi
Registration #5	2017-10-12	45.678 mi
Registration #6	2018-10-09	52.465 mi
Registration #7	2018-10-09	52.466 mi
Registration #8	2019-10-09	52.466 mi
Registration #9	2019-10-09	52.466 mi
Registration #10	2019-10-09	52.466 mi
Registration #11	2019-10-09	52.466 mi
Registration #12	2019-10-09	52.466 mi
Registration #13	2019-10-09	52.466 mi
Registration #14	2019-10-09	52.466 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1295 kg
Max. allowed weight	1765 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	A580J057