



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ADAM ENERGISED
Colour	Green
Year of manufacture	2017
Top speed	102 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.229 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	125 g/km
CO2 label	D








Internet history

Entry 1

Date	2021-09-15
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	4

MOT #6	2023-10-06 07:43
MOT test number	513150031298
Result	✓ Passed
Next expiry date	2024-10-05
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement Top mount (5.3.4 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))

**MOT #5**

2023-09-26 10:58

MOT test number

668771379350

Result**✗ Failed****Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement Top mount (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4**

2022-09-14 12:20

MOT test number

972566295717

Result**✓ Passed****Advice** Front Shock absorbers has light misting of oil both (5.3.2 (b))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3**

2021-09-23 16:49

MOT test number

179972913598

Result**✓ Passed****MOT #2**

2021-02-03 13:45

MOT test number

166540682754

Result**✓ Passed**



MOT #1	2020-02-28 14:36
MOT test number	205170881772
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	SD17ZGO
Plate since	2019-03-29
Current registration	SD17ZGO
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-30
Last registration	2023-10-06
Complete history	See info



Registration #1	2017-03-30	28 mi
Registration #2	2020-02-28	26.276 mi
Registration #3	2021-02-03	34.583 mi
Registration #4	2022-02-28	35.277 mi
Registration #5	2022-02-28	35.277 mi
Registration #6	2022-02-28	35.277 mi
Registration #7	2022-02-28	35.277 mi
Registration #8	2023-10-06	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1966 mm
Height	1483 mm
Length	3698 mm
Wheel base	2311 mm
Kerb weight	1011 kg
Max. allowed weight	1470 kg

Additional information

Fuel tank capacity	38 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	B12XER -19NN8638LWD