






General information

| Make | FIAT |
|---------------------|----------------|
| Model | PANDA POP |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 102 mph |
| 0 - 60 mph | 14.2 seconds |
| Gearbox | 5 speed Manual |
| | |

Engine & fuel consumption

| Power | 69 BHP |
|-------------------------|----------|
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-10-27 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk



MOT history

| MOT expiry date | 2024-10-19 |
|--------------------|------------|
| MOT pass rate | 63 % |
| MOT passed | 5 |
| Failed MOT tests | 3 |
| Total advice items | 4 |
| Total items failed | 6 |

| MOT #8 | 2023-09-27 11:52 |
|------------------|------------------|
| MOT test number | 731692430483 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-19 |

| MOT #7 | 2023-09-27 11:52 |
|-------------------------|---|
| MOT test number | 395913070007 |
| Result | × Failed |
| Pass with rectification | Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Pass with rectification | Nearside Rear Brake cable insecure (1.1.15 (c)) |

| MOT #6 | 2022-09-23 11:02 |
|-----------------|------------------|
| MOT test number | 807743806087 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2021-10-20 15:46 |
| MOT test number | 252425260514 |

| MOT test number | 252425260514 |
|-----------------|--------------|
| Result | ✓ Passed |





| MOT #4 | | 2020-10-08 11:31 |
|----------|--|------------------|
| MOT test | number | 516955941955 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #3 | 2020-10-08 11:29 |
|---|------------------|
| MOT test number | 837831165507 |
| Result | 🗙 Failed |
| Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #2 | 2020-10-08 09:13 |
|--|------------------|
| MOT test number | 288140754052 |
| Result | 🗙 Failed |
| Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))Fail Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c)) | |

| MOT #1 | 2019-10-10 09:20 |
|-----------------|------------------|
| MOT test number | 161931236918 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 February 2025 | ✓ MOT Expires: 19 October 2024 |
|---|---|
| Tax status | Valid until 1 February |
| Days left | 279 |
| MOT expiry date | 19 October 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---|------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| | 4 | |
| Date | | 1.E |
| Category | | amt |
| Туре | | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 10 |
| First mileage registration | 2016-09-29 |
| Last registration | 2023-09-27 |
| Complete history | <u>See info</u> |



| Registration #1 | 2016-09-29 | 25 mi |
|------------------|------------|------------|
| Registration #2 | 2019-10-10 | 21.539 mi |
| Registration #3 | 2020-10-08 | 33.317 mi |
| Registration #4 | 2020-10-08 | 33.317 mi |
| Registration #5 | 2020-10-08 | 33.317 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |
| Registration #10 | | 11.377 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 82% |
| Children | 63% |
| Pedestrian | 49% |
| Safety systems | 43% |
| Overall rating | 68% |
| Video | see crash video |



| Dimensions & weight | |
|---------------------------------|-----------------------|
| Width | 1882 mm |
| Height | 1551 mm |
| Length | 3653 mm |
| Wheel base | 2300 mm |
| Kerb weight | 1015 kg |
| Max. allowed weight | 1420 kg |
| Additional information | |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Engine number Carcheck.co.uk | 1523903 page 11/11 |