





report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Grey
Year of manufacture	2010
Top speed	129 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2022-02-03

Pictures 5

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2022-01-07
Pictures	5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-08-22
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #12	2023-08-18 07:27
MOT test number	290296961240
Result	✓ Passed
Next expiry date	2024-08-22

MOT #11	2022-08-23 15:00
MOT test number	209919408943
Result	✓ Passed

MOT #10	2022-08-23 10:17
MOT test number	107107452845
Result	X Failed
Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its stru	ucture (5.2.3 (d) (ii))
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #9	2021-11-24 17:27
MOT test number	671092443039
Result	✓ Passed
MOT #8	2020-12-12 16:02
MOT test number	502143293719
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7	2019-12-16 09:14
MOT test number	177459824706
Result	✓ Passed
MOT #6	2018-08-22 11:29
MOT test number	441805203508
Result	✓ Passed
MOT #5	2017-09-01 11:54
MOT test number	603614054816
Result	✓ Passed
Advice Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2016-09-07 11:01
MOT test number	181640118817
Result	✓ Passed
MOT #3	2015-09-03 10:05
MOT test number	115435215265
Result	✓ Passed

	2014-08-21 10:31
number	697683534223
	✓ Passed
Engine covers fitted obscuring some components in the engine bay	
Rear Tyre worn close to the legal limit (4.1.E.1)	
Nearside rear tyre worn on inner edge	
Under-trays fitted obscuring some underside components	
Offside rear tyre worn on inner edge	
	Engine covers fitted obscuring some components in the engine bay Rear Tyre worn close to the legal limit (4.1.E.1) Nearside rear tyre worn on inner edge Under-trays fitted obscuring some underside components

CarCheck.co.uk page 4/12



MOT #1 2013-09-09 14:34

MOT test number 349482453468

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	hictor.
UMMIAI	nisiaiv

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	NIE NIE
Plate since	
Current registration	NE UK
Flate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-13
Last registration	2023-08-18
Complete history	See info



Registration #1	2010-09-13	11 mi
Registration #2	2013-09-09	22.249 mi
Registration #3	2014-08-21	26.930 mi
Registration #4	2015-09-03	32.898 mi
Registration #5	2016-09-07	37.695 mi
Registration #6	2017-09-01	41.325 mi
Registration #7	2018-08-22	43.493 mi
Registration #8	2019-12-16	44.607 mi
Registration #9		9.77 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		11,777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1593 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	N22B13200367

CarCheck.co.uk page 12/12