



OLZ575


report date: 2024-03-29

General information

Make	MINI
Model	COUNTRYMAN COOPER D ALL4 AUTO COOPER D ALL4
Colour	Black
Year of manufacture	2011
Top speed	110 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-17
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-03
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	22
Total items failed	4

MOT #14	2023-04-28 09:25
MOT test number	715679170111
Result	✓ Passed
Next expiry date	2024-05-03
Advice	Washer poor
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2022-04-27 10:48
MOT test number	213570825874
Result	✓ Passed

MOT #12	2022-04-27 09:04
MOT test number	336393730368
Result	✗ Failed
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Offside Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #11** 2021-05-04 10:26**MOT test number** 311940326311**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 205/60/16 STRONG ADVISE (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #10** 2021-05-04 10:26**MOT test number** 305946911642**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 205/60/16 STRONG ADVISE (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9** 2020-01-02 15:27**MOT test number** 197978781823**Result** ✓ Passed**MOT #8** 2019-05-07 10:59**MOT test number** 167255027919**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2019-05-07 10:59**MOT test number** 696071063358**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2018-01-03 13:59**MOT test number** 878782952020**Result** ✓ Passed**MOT #5** 2017-08-17 14:11**MOT test number** 108715071516**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-08-16 11:59**MOT test number** 909337356759**Result** ✗ Failed**Fail** Emissions not tested engine noise. (7.3.A.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-04-08 13:18**MOT test number** 909048194486**Result** ✓ Passed



MOT #2	2015-07-30 09:31
MOT test number	201201177465
Result	✓ Passed
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #1	2014-08-28 11:09
MOT test number	969920444294
Result	✓ Passed
Notice	Emissions to clean to register



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
3 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	3 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-08-12
Last registration	2023-04-28
Complete history	See info



Registration #1	2011-08-12	17 mi
Registration #2	2014-08-28	27.012 mi
Registration #3	2015-07-30	38.010 mi
Registration #4	2016-04-08	45.823 mi
Registration #5	2017-08-16	65.244 mi
Registration #6	2017-08-17	65.244 mi
Registration #7	2018-01-03	65.835 mi
Registration #8	2019-05-07	83.578 mi
Registration #9	2019-05-07	83.578 mi
Registration #10	2019-05-07	83.578 mi
Registration #11	2019-05-07	83.578 mi
Registration #12	2019-05-07	83.578 mi
Registration #13	2019-05-07	83.578 mi
Registration #14	2019-05-07	83.578 mi
Registration #15	2019-05-07	83.578 mi
Registration #16	2019-05-07	83.578 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1405 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

75307762