




report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D S
Colour	Grey
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G





MOT history

MOT expiry date	2025-03-12
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	33
Total items failed	3

MOT #18 2024-03-12 11:15

MOT test number 387998779359

Result ✓ Passed

Next expiry date 2025-03-12

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #17 2023-03-13 13:03

MOT test number 588584155904

Result ✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Centre exhaust tatty
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Under vehicle and brake pipes surface corrosion

**MOT #16**

2023-03-11 10:42

MOT test number

286200105716

Result**✗ Failed****Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Centre exhaust tatty**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Under vehicle and brake pipes surface corrosion**MOT #15**

2022-02-24 16:17

MOT test number

433984650222

Result**✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bushes (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14**

2021-03-03 08:48

MOT test number

354459121518

Result**✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened inner edges (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bushes (5.3.4 (a) (i))**Advice** Exhaust outer skin poor but not leaking**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2020-01-27 11:12**MOT test number** 793599047919**Result** ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12 2019-02-13 11:54**MOT test number** 111279557475**Result** ✓ Passed**MOT #11** 2018-07-19 14:25**MOT test number** 209519410348**Result** ✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2017-07-08 11:57**MOT test number** 875708918081**Result** ✓ Passed

Advice Offside Front Oil leak

Advice Engine covers and undertrays

**MOT #9** 2017-07-08 11:07**MOT test number** 660914835211**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Oil leak**Advice** Offside Rear Rear position lamp(s) obscured but not more than 50% (1.1.A.3c)**Advice** Engine covers and undertrays**MOT #8** 2016-07-04 10:12**MOT test number** 820788092080**Result** ✓ Passed**MOT #7** 2015-06-29 17:18**MOT test number** 909710085184**Result** ✓ Passed**MOT #6** 2015-06-29 10:55**MOT test number** 858780585187**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2014-06-27 09:52**MOT test number** 207928374460**Result** ✓ Passed**Notice** Front & rear brake pads appear low - please check**MOT #4** 2013-06-20 10:08**MOT test number** 409901273106**Result** ✓ Passed



MOT #3	2012-06-13 11:37
MOT test number	607835062180
Result	✓ Passed
<div>NoticeN/s/f sidewall deteriorated</div>	

MOT #2	2011-06-23 14:17
MOT test number	159864371183
Result	✓ Passed

MOT #1	2010-07-12 16:48
MOT test number	323333590173
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
12 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-03-29
Current registration	 
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-07
Last registration	2024-03-12
Complete history	See info



Registration #1	2007-12-07	23 mi
Registration #2	2010-07-12	18.827 mi
Registration #3	2011-06-23	26.132 mi
Registration #4	2012-06-13	32.777 mi
Registration #5	2013-06-20	39.286 mi
Registration #6	2014-06-27	48.181 mi
Registration #7	2015-06-29	56.751 mi
Registration #8	2015-06-29	56.751 mi
Registration #9	2016-07-04	65.203 mi
Registration #10	2017-07-08	81.242 mi
Registration #11	2018-06-20	95.277 mi
Registration #12	2019-06-20	105.277 mi
Registration #13	2020-06-20	115.277 mi
Registration #14	2021-06-20	125.277 mi
Registration #15	2022-06-20	135.277 mi
Registration #16	2023-06-20	145.277 mi
Registration #17	2024-03-12	155.277 mi
Registration #18		
Registration #19		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	130531