





report date: 2024-03-28

General information

Make	VOLVO
Model	V90 D4 CROSS COUNTRY AWD
Colour	Silver
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	8.5 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/10



Internet history

Entry	1
-------	---

End y 1	
Date	2021-08-23
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/10



MOT	history
1.101	iliocol y

MOT expiry date	2024-08-24
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	1
Total items failed	0

MOT #5	2023-08-21 13:48
MOT test number	876985031575
Result	✓ Passed
Next expiry date	2024-08-24
Minor Nearside Front Outer Track rod end ball joint dust cover damaged of the ingress of dirt (2.1.3 (g) (i))	or deteriorated, but preventing

MOT #4	2022-08-17 14:48
MOT test number	491084697567
Result	✓ Passed
MOT #3	2021-08-25 15:46
MOT test number	269962896227
Result	✓ Passed
MOT #2	2020-11-20 10:46
MOT test number	805383538937
Result	✓ Passed

MOT #1	2019-11-29 13:53
MOT test number	158281777961
Result	✓ Passed

CarCheck.co.uk page 3/10



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2016-12-28
Last registration	2023-08-21
Complete history	See info



Registration #1	2016-12-28	17 mi
Registration #2	2019-11-29	33.832 mi
Registration #3	2020-11-20	47.163 mi
Registration #4		77,777 66
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		0.77 66

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1895 mm
Height	1543 mm
Length	4936 mm
Wheel base	2941 mm
Kerb weight	1826 kg
Max. allowed weight	2420 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1878896

CarCheck.co.uk page 10/10