



report date: 2024-03-29

General information

Make	LAND ROVER
Model	FREELANDER TD4 XS
Colour	Black
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	11.7 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 150 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-19
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-02
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	48
Total items failed	4

MOT #13 2024-04-03 14:47

MOT test number 474245458533

Result ✓ Passed

Next expiry date 2025-04-02

Advice Oil leak, but not excessive rear diff (8.4.1 (a) (i))**Advice** Front Sub-frame corroded but not seriously weakened and rear (5.3.3 (b) (i))

MOT #12 2024-04-02 14:37

MOT test number 571680730238

Result ✗ Failed**Fail** Parking brake lever inoperative (1.1.6 (d))**Advice** Front Sub-frame corroded but not seriously weakened and rear (5.3.3 (b) (i))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Oil leak, but not excessive rear diff (8.4.1 (a) (i))

**MOT #11**

2022-09-23 14:30

MOT test number

113396800337

Result

✓ Passed

- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Upper Suspension component mounting prescribed area is corroded but not considered excessive macpherson strut mounting area (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge reading 2.0mm (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge reading 2.5mm (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge reading 1.6mm(on legal limit) (5.2.3 (e))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Upper Suspension component mounting prescribed area is corroded but not considered excessive macpherson strut mounting area (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge reading 3.0mm (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2022-09-23 14:30

MOT test number

838513850070

Result**✗ Failed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Upper Suspension component mounting prescribed area is corroded but not considered excessive macpherson strut mounting area (5.3.6 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge reading 1.6mm(on legal limit) (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge reading 3.0mm (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Upper Suspension component mounting prescribed area is corroded but not considered excessive macpherson strut mounting area (5.3.6 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge reading 2.0mm (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge reading 2.5mm (5.2.3 (e))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2021-06-29 15:22**MOT test number** 542088081233**Result** ✓ Passed**MOT #8** 2021-01-16 11:17**MOT test number** 762439062148**Result** ✓ Passed**MOT #7** 2020-01-20 14:08**MOT test number** 817036823534**Result** ✓ Passed**MOT #6** 2019-02-08 12:11**MOT test number** 646691218960**Result** ✓ Passed**Advice** Fuel cap half broken but sealing**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2018-02-15 11:58**MOT test number** 976080715173**Result** ✓ Passed**MOT #4** 2017-02-14 14:13**MOT test number** 588002492071**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2016-02-22 09:28
MOT test number	324497843435
Result	✓ Passed
MOT #2	2015-02-06 12:02
MOT test number	916697435071
Result	✓ Passed
MOT #1	2014-02-19 15:05
MOT test number	625190054035
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
2 April 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-17
Last registration	2024-04-03
Complete history	See info



Registration #1	2011-03-17	12 mi
Registration #2	2014-02-19	16.292 mi
Registration #3	2015-02-06	20.259 mi
Registration #4	2016-02-22	24.571 mi
Registration #5	2017-02-14	34.424 mi
Registration #6	2018-02-15	44.740 mi
Registration #7	2019-02-08	57.080 mi
Registration #8	2020-01-20	66.959 mi
Registration #9	2020-05-20	75.377 mi
Registration #10	2020-05-20	75.377 mi
Registration #11	2020-05-20	75.377 mi
Registration #12	2020-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2020-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ794013534224DT