



report date: 2024-03-29

General information

Make	ABARTH
Model	PUNTO ABARTH
Colour	White
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	201 Nm at 5.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-04
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-04-16
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	17
Total items failed	9

MOT #15 2023-04-05 11:36

MOT test number 889783298011

Result ✓ Passed

Next expiry date 2024-04-16

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2023-04-04 09:02

MOT test number 280936574547

Result ✗ Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #13**

2022-04-14 14:46

MOT test number

998487659625

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Inner WHEEL DAMAGED**MOT #12**

2022-04-14 09:12

MOT test number

929273715696

Result

✗ Failed

Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Inner WHEEL DAMAGED**Minor** Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))**MOT #11**

2021-04-14 11:59

MOT test number

111990903467

Result

✓ Passed

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Coil spring corroded lower section (5.3.1 (b) (i))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Coil spring corroded lower section (5.3.1 (b) (i))**MOT #10**

2020-04-01 09:40

MOT test number

838846518913

Result

✓ Passed

**MOT #9** 2019-04-15 11:30**MOT test number** 681912220601**Result** ✓ Passed**MOT #8** 2019-04-15 08:21**MOT test number** 602049918647**Result** ✗ Failed

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

MOT #7 2018-04-13 08:40**MOT test number** 481734488779**Result** ✓ Passed**MOT #6** 2017-04-08 08:06**MOT test number** 399831807686**Result** ✓ Passed**MOT #5** 2016-04-16 10:27**MOT test number** 325064819640**Result** ✓ Passed**MOT #4** 2015-04-14 08:43**MOT test number** 495274605103**Result** ✓ Passed**MOT #3** 2014-04-16 08:35**MOT test number** 596596004110**Result** ✓ Passed

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)



MOT #2	2014-04-16 08:35
MOT test number	259746904154
Result	✗ Failed
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Nearside Headlamp aim too low and too far to the left. (1.8)
Advice	Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

MOT #1	2013-04-15 08:28
MOT test number	239045903115
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✗
MOT
Expired:
16 April 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	16 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-16
Last registration	2023-04-05
Complete history	See info



Registration #1	2010-04-16	13 mi
Registration #2	2013-04-15	25.572 mi
Registration #3	2014-04-16	37.956 mi
Registration #4	2015-04-14	45.093 mi
Registration #5	2016-04-16	56.749 mi
Registration #6	2017-04-08	66.962 mi
Registration #7	2018-04-13	74.759 mi
Registration #8	2019-04-15	77.399 mi
Registration #9	2020-04-16	78.337 mi
Registration #10	2021-04-16	79.337 mi
Registration #11	2022-04-16	80.337 mi
Registration #12	2023-04-16	81.337 mi
Registration #13	2024-04-16	82.337 mi
Registration #14	2025-04-16	83.337 mi
Registration #15	2026-04-16	84.337 mi
Registration #16	2027-04-16	85.337 mi

More info >



Dimensions & weight

Width	1726 mm
Height	1490 mm
Length	4041 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1507284