






## General information

Make	VAUXHALL
Model	AGILA SE
Colour	Red
Year of manufacture	2013
Top speed	106 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	131 g/km
CO2 label	E







## Internet history

Entry 1

Date Pictures 2022-04-24

27

Listing price

View report



source: cargurus.co.uk





# MOT history

MOT expiry date	2025-04-19
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	10
Total items failed	0

MOT #11	2024-04-15 10:23
MOT test number	900044289660
Result	✓ Passed
Next expiry date	2025-04-19

MOT #10		2024-04-05 14:12
MOT test	number	555712826124
Result		🗙 Failed
Advice	Rear Registration plate deteriorated but not likely to be misread cracked (0.1 (b	))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge both edges worn (5.2.	3 (e))
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	vice Offside Rear Tyre worn close to legal limit/worn on edge ON LIMIT 185/60/15 (5.2.3 (e))	
MAJOR	Offside Front Coil spring fractured or broken lwr part missing. (5.3.1 (b) (i))	

МОТ #9	2023-04-05 11:53
MOT test number	279906594906
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread crack	red (0.1 (b))





MOT #8	2023-04-05 10:14	
MOT test number	920271478006	
Result	🗙 Failed	
Advice Offside Front Tyre worn close to legal limit/worn on edge aprox' 2.5mm (5.2.3 (e))		
<b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm 18	35/60/15 (5.2.3 (e))	
Advice Rear Registration plate deteriorated but not likely to be misread cracked	d (0.1 (b))	

MOT #7	2022-04-20 19:14
MOT test number	874175763749
Result	✓ Passed

MOT #6	2021-05-21 08:24
MOT test	number 767427591442
Result	✓ Passed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #5	2020-05-28 08:35
MOT test number	617232351121
Result	✓ Passed
MOT #4	2010 00 0E 00.E4

MOT #4	2019-09-05 08:54
MOT test number	670246317356
Result	✓ Passed

МОТ #3	2018-10-06 10:28
MOT test number	637510914880
Result	✓ Passed





MOT #2	2017-10-07 10:43
MOT test number	346659844551
Result	✓ Passed
MOT #1	2016-10-10 14:16
MOT test number	685631227279
Result	✓ Passed





Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 June 2024	Expires: 19 April 2025
Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 April 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
AND	
**********	
NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-10
Last registration	2024-04-15
Complete history	See info



Registration #1	2013-12-10	17 mi
Registration #2	2016-10-10	14.103 mi
Registration #3	2017-10-07	18.594 mi
Registration #4	2018-10-06	23.963 mi
Registration #5	2019-09-05	29.684 mi
Registration #6	2020-05-28	32.760 mi
Registration #7	2021-05-21	36.576 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		10.200 au





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5