





report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 COUPE SE
Colour	Black
Year of manufacture	2007
Top speed	138 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	220 Nm at 4.150 rpm
Engine capacity	2.230 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	40.9 mpg
Consumption combined	30.7 mpg
CO2 emission	219 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history


Entry 1

Date 2021-08-09

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-08-05
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	14
Total items failed	10

MOT #19	2023-08-01 08:18
MOT test number	270043806284
Result	✓ Passed
Next expiry date	2024-08-05
Advice - Corrosion inhibitor application applied to underbody/suspension	

MOT #18	2022-08-03 10:18
MOT test number	195932122044
Result	✓ Passed
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge - Wearing tread (5.2.3 (e))	on edge than across
Advice - Corrosion application inhibitor applied randomly underbody and chassis	

MOT #17		2021-08-06 14:09
MOT test i	number	435936295275
Result		✓ Passed
MOT #16		2020-12-01 14:20
MOT test i	number	751778662724
Result		✓ Passed
Advice	Both nearside tyres outer side walls poor condition	
Advice	Brake fluid low	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #15	2019-12-18 11:30
MOT test number	915095036471
Result	✓ Passed
Advice Rear brake discs corroded	

MOT #14		2019-12-18 11:30
MOT test number		532255274993
Result		× Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear brake discs	corroded	

MOT #13	2018-12-11 15:48
MOT test number	296756904590
Result	✓ Passed
MOT #12	2018-03-20 13:24
MOT test number	135968372765
Result	✓ Passed
Advice Scratchin windsceen	

Advice Scratchin windsceen	
MOT #11	2017-02-24 17:59
MOT test number	193264897230
Result	✓ Passed
MOT #10	2016-03-24 17:20
MOT test number	864213951496
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9		2015-03-24 16:06
MOT test	number	848053585082
Result		✓ Passed
MOT #8		2014-05-19 14:23
MOT test	number	156139234107
Result		✓ Passed
MOT #7		2013-05-29 11:48
MOT test	number	785669043196
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #6	2012-04-04 18:23
MOT test number	585645392058
Result	✓ Passed
Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)	

MOT #5	2012-04-03 13:32
MOT test number	946474292081
Result	× Failed
Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2) Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)	

MOT #4	2011-04-07 17:36
MOT test number	357917291079
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3 2011-04-05 14:17 **MOT** test number 176505691020 Result × Failed Fail Nearside Front Front position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2

MOT test number

170665480461

Result

Notice

Off side front discs wearing/off side front tyre wearing/both sides rear discs wearing

MOT #1

MOT test number

940003380045

Result

Notice Off side front discs wearing/off side front tyre wearing/both sides rear discs wearing

Fail Nearside brake disc excessively scored (3.5.1h)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
venicle class	70
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

PK07ZDR

report date: 2024-03-28

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

More info >



PK07ZDR report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-05
Last registration	2023-08-01
Complete history	See info



Registration #1	2007-04-05	16 mi
Registration #2	2010-03-24	17.294 mi
Registration #3	2010-03-26	17.294 mi
Registration #4	2011-04-05	20.540 mi
Registration #5	2011-04-07	20.540 mi
Registration #6	2012-04-03	22.461 mi
Registration #7	2012-04-04	22.461 mi
Registration #8	2013-05-29	23.725 mi
Registration #9	2014-05-19	24.120 mi
Registration #10	2015-03-24	24.487 mi
Registration #11	2016-03-24	26.751 mi
Registration #12		11.117 es
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		
Registration #20		n.m.

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1868 mm
Height	1399 mm
Length	4815 mm
Wheel base	2725 mm
Kerb weight	1600 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/1

Number of axles 2

Engine number LJ431433739