





report date: 2024-03-29

General information

| Make | NISSAN |
|---------------------|-------------------|
| Model | LEAF ACENTA |
| Colour | Red |
| Year of manufacture | 2016 |
| Top speed | 87 mph |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| Power | 107 BHP |
|-------------|----------------------|
| Max. torque | 254 Nm at 10.500 rpm |
| Fuel type | Electricity |



CarCheck.co.uk page 1/11



HY16XBU

report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-14

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



HY16XBU

report date: 2024-03-29

| MC | TC | history | |
|----|----|---------|--|
|----|----|---------|--|

| MOT expiry date | 2025-04-11 |
|--------------------|------------|
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 5 |
| Total items failed | 3 |

| MOT #10 | 2024-04-12 15:13 |
|------------------|------------------|
| MOT test number | 130443309171 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-11 |

| MOT #9 | 2023-07-19 15:57 |
|-----------------|------------------|
| MOT test number | 696873336319 |
| Result | ✓ Passed |

| MOT #8 | 2023-07 | 7-19 15:57 |
|-------------------------|---|-----------------|
| MOT test number | 8913 | 15402751 |
| Result | | X Failed |
| Pass with rectification | Offside Windscreen washer provides insufficient washer liquid (3.5 (a)) | |

Pass with rectification Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

| MOT #7 | | 2022-07-19 09:04 |
|------------|--|---------------------------------|
| MOT test n | number | 165727623654 |
| Result | | ✓ Passed |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in | n excessive movement (5.3.4 (a) |

CarCheck.co.uk page 3/11



HY16XBU

report date: 2024-03-29

Passed

MOT #6 2021-07-20 13:46

MOT test number 926389352043

Result ✓ Passed

MOT #5 2021-07-20 13:32

MOT test number 864496204108

Result X Failed

MAJOR Central Rear Seat belt not functioning as intended (7.1.2 (c))

MOT #4 2021-03-08 11:20

MOT test number 548832471747

Result Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-02-24 13:04

MOT test number 673871188337

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Advice Front wipers worn but still clearing screen

Result

MOT #2 2019-03-14 09:50

MOT test number 430821049089

Result \(\sqrt{Passed} \)

MOT #1 2019-03-14 09:50

MOT test number 862044977968


Result X Failed

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Days left 337
MOT expiry date 11 April 2025

Full MOT history See MOT history

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Tyne | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full re | | N |
|---|-----------|---|
| | | |
| | | |
| *************************************** | | |
| | | |
| ******** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes See in this check if this NISSAN had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2016-03-15 |
| Last registration | 2024-04-12 |
| Complete history | See info |



| Registration #1 | 2016-03-15 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2019-03-14 | 55.504 mi |
| Registration #3 | 2019-03-14 | 55.504 mi |
| Registration #4 | 2020-02-24 | 57.316 mi |
| Registration #5 | 2021-03-08 | 60.181 mi |
| Registration #6 | | 71.777 66 |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 66 |
| Registration #9 | | 9.777 es |
| Registration #10 | | 71.777 66 |
| Registration #11 | | 9.77 es |
| Registration #12 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 83% |
| Pedestrian | 65% |
| Safety systems | 84% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1550 mm |
| Length | 4445 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1538 kg |
| Max. allowed weight | 1945 kg |

Additional information

| Fuel delivery | Not Applicable | |
|-----------------------------------|----------------|------------|
| Number of doors | 5 | |
| Number of seats | 5 | |
| Number of axles Carcheck.co.uk | 2 | page 11/11 |