



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 EXCLUSIVE HDI
Colour	Black
Year of manufacture	-
Top speed	134 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	370 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-10
Pictures	37
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #19 2023-04-11 14:47

MOT test number 300544661719

Result ✓ Passed

Next expiry date 2024-04-22

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Offside Front brake pad wear wiring broken
- Advice** Offside Front back rest has slight movement
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front door interior handle broken
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge 245/40 r18 97y (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear park brake cable not located correctly
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #18**

2023-04-06 08:11

MOT test number

901385994329

Result

✗ Failed

- Advice** Offside Front back rest has slight movement
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front door interior handle broken
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Rear park brake cable not located correctly
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge 245/40 r18 97y (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front brake pad wear wiring broken

MOT #17

2022-04-23 10:22

MOT test number

106160101547

Result

✓ Passed

MOT #16

2021-10-06 11:30

MOT test number

966220359417

Result

✓ Passed

**MOT #15** 2021-09-17 14:12**MOT test number** 194977725799**Result** ✗ Failed**Advice** Front Shock absorbers has a reduced damping effect (5.3.2 (d))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #14** 2021-03-08 09:59**MOT test number** 680085439047**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-03-02 11:18**MOT test number** 972500457005**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2019-03-25 11:33**MOT test number** 413008593205**Result** ✓ Passed**Advice** Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake cable damaged but not to excess slight wear from suspension mount (1.1.15 (a))

**MOT #11** 2018-04-30 09:44**MOT test number** 967956752484**Result** ✓ Passed**MOT #10** 2018-04-25 08:53**MOT test number** 719015834264**Result** ✗ Failed**Fail** Nearside Rear Inner Rear position lamp(s) not working (1.1.A.3b)**MOT #9** 2017-04-19 10:37**MOT test number** 514173861387**Result** ✓ Passed**Advice** Nearside Rear tyre worn on inner edge and slightly perished**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2016-04-18 09:00**MOT test number** 833809385683**Result** ✓ Passed**Advice** Nearside rear tyre wearing on the outer edge**MOT #7** 2015-04-28 14:40**MOT test number** 995478015107**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Nearside front tyre has perished.**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Nearside rear tyre has perished.

**MOT #6** 2015-04-28 14:40**MOT test number** 117658115104**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Nearside front tyre has perished.**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre has perished.**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #5** 2014-04-29 10:13**MOT test number** 665249514183**Result** ✓ Passed**MOT #4** 2013-04-17 09:59**MOT test number** 755497003156**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** The n/s/r door is damaged**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-05-05 11:43**MOT test number** 209226422131**Result** ✓ Passed



MOT #2	2011-09-19 15:22
MOT test number	779772861297
Result	✓ Passed

MOT #1	2011-09-16 11:08
MOT test number	676709451250
Result	✗ Failed
<div><div>Notice</div> Nail in offside rear tyre</div> <div><div>Advice</div> Nearside Rear Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Notice</div> Oil leak</div> <div><div>Fail</div> Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)</div> <div><div>Advice</div> Offside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-01
Last registration	2023-04-11
Complete history	See info



Registration #1	2008-09-01	16 mi
Registration #2	2011-09-16	31.704 mi
Registration #3	2011-09-19	31.711 mi
Registration #4	2012-05-05	38.131 mi
Registration #5	2013-04-17	46.424 mi
Registration #6	2014-04-29	55.655 mi
Registration #7	2015-04-28	61.504 mi
Registration #8	2016-04-18	67.282 mi
Registration #9	2017-04-19	73.382 mi
Registration #10	2018-04-25	79.702 mi
Registration #11	2019-05-20	86.222 mi
Registration #12	2020-05-20	92.922 mi
Registration #13	2021-05-20	99.792 mi
Registration #14	2022-05-20	106.722 mi
Registration #15	2023-05-20	113.712 mi
Registration #16	2024-05-20	120.762 mi
Registration #17	2025-05-20	127.872 mi
Registration #18	2026-05-20	135.042 mi
Registration #19	2027-05-20	142.272 mi
Registration #20	2028-05-20	149.562 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1471 mm
Length	4829 mm
Wheel base	2815 mm
Kerb weight	1765 kg
Max. allowed weight	2352 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ604003384