



report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 DCI SE
Colour	White
Year of manufacture	2012
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	58.9 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-15
Pictures	27
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-05
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	23
Total items failed	24

MOT #17	2024-02-06 13:15
MOT test number	640135752830
Result	✓ Passed
Next expiry date	2025-02-05
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #16	2024-02-02 14:56
MOT test number	396404626554
Result	✗ Failed
Fail	Stop lamp(s) all not working (4.3.1 (a) (iii))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))



MOT #15	2023-01-24 17:06
MOT test number	348268292118
Result	✓ Passed
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14	2022-03-21 14:33
MOT test number	872527713734
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2022-03-04 10:11

MOT test number

530357520086

Result**✗ Failed**

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre is not of commercial construction
- Advice** Spare tyre defective
- Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre is not of commercial construction
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm: pin / bush debonding, not resulting in excessive movement
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2021-03-18 10:04

MOT test number

259681207259

Result**✓ Passed**

**MOT #11** 2021-03-18 10:04**MOT test number** 329685719484**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #10** 2020-03-26 10:25**MOT test number** 964177387242**Result** ✓ Passed**MOT #9** 2019-03-14 12:41**MOT test number** 227804586734**Result** ✓ Passed**MOT #8** 2019-03-14 12:41**MOT test number** 867336264298**Result** ✗ Failed**Pass with rectification** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Pass with rectification** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #7** 2018-03-29 13:09**MOT test number** 608994453800**Result** ✓ Passed

**MOT #6** 2018-03-29 13:09**MOT test number** 987705779179**Result** ✗ Failed**Pass with rectification** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2017-03-16 13:32**MOT test number** 245907749555**Result** ✓ Passed**MOT #4** 2017-03-16 13:32**MOT test number** 411878456330**Result** ✗ Failed**Pass with rectification** Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2016-03-24 13:00**MOT test number** 695471849212**Result** ✓ Passed**Advice** Under trays and engine covers**Advice** Front Anti-roll bar linkage has slight play in a ball joint both (2.4.G.2)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



MOT #2	2016-03-22 11:04
MOT test number	874691238132
Result	✗ Failed
Advice	Front Anti-roll bar linkage has slight play in a ball joint both (2.4.G.2)
Fail	Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
Advice	Under trays and engine covers
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #1	2015-03-17 10:13
MOT test number	169146475032
Result	✓ Passed
Advice	Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

X

Untaxed

Tax expired:
6 April 2024

✓

MOT

Expires:
5 February 2025

Tax status	Expired at 6 April 2024
Days left	24 days too late
MOT expiry date	5 February 2025
Full MOT history	See MOT history



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-29
Last registration	2024-02-06
Complete history	See info



Registration #1	2012-03-29	19 mi
Registration #2	2015-03-17	79.785 mi
Registration #3	2016-03-22	106.015 mi
Registration #4	2016-03-24	106.015 mi
Registration #5	2017-03-16	109.188 mi
Registration #6	2017-03-16	109.188 mi
Registration #7	2018-03-29	112.670 mi
Registration #8	2018-03-29	112.670 mi
Registration #9	2019-03-14	115.755 mi
Registration #10	2019-03-14	115.755 mi
Registration #11	2019-03-14	115.755 mi
Registration #12	2019-03-14	115.755 mi
Registration #13	2019-03-14	115.755 mi
Registration #14	2019-03-14	115.755 mi
Registration #15	2019-03-14	115.755 mi
Registration #16	2019-03-14	115.755 mi
Registration #17	2019-03-14	115.755 mi
Registration #18	2019-03-14	115.755 mi
Registration #19	2019-03-14	115.755 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2011 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1261 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Number of axles	2
Engine number	K9K-020445