



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-07
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-12
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	58
Total items failed	15

MOT #20	2023-08-09 10:08
MOT test number	548371638205
Result	✓ Passed
Next expiry date	2024-08-12
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #19	2023-08-08 10:48
MOT test number	917958212109
Result	✗ Failed
MAJOR	Offside Front Coil spring fractured or broken broken (5.3.1 (b) (i))
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

**MOT #18**

2022-08-11 13:17

MOT test number

771944430221

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bush starting to become unbonded (5.3.4 (a) (i))

MOT #17

2022-08-10 12:45

MOT test number

896379738631

Result

✗ Failed

MAJOR Nearside Front Suspension arm pin or bush excessively worn bush unbonded (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bush starting to become unbonded (5.3.4 (a) (i))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Front Headlamp aim not tested due to head lamps not working on dip beam (4.1.2 (b))

MOT #16

2021-08-13 12:57

MOT test number

843792993912

Result

✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #15**

2021-08-12 10:53

MOT test number

743014231931

Result**✗ Failed**

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #14

2020-11-16 16:13

MOT test number

649515569154

Result**✓ Passed**

- Advice** Chip in windscreen zone (b)
- Advice** Nearside Inner slight play in track rod

MOT #13

2020-11-16 12:07

MOT test number

560313056898

Result**✗ Failed**

- Advice** Chip in windscreen zone (b)
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Inner slight play in track rod
- MAJOR** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction wipers parking in the swept area (3.1 (a) (ii))
- MAJOR** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

**MOT #12** 2019-05-21 11:52**MOT test number** 996803181409**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MOT #11** 2018-07-05 15:07**MOT test number** 312806105839**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Items removed from driver's view prior to test**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #10** 2017-06-15 15:26**MOT test number** 321696310409**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #9**

2017-06-15 11:50

MOT test number

863134407608

Result**✗ Failed****Advice**

Items removed from driver's view prior to test

Fail

Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice

Vehicles internal headlight adjuster altered to recheck lights

Fail

Nearside Rear coil spring broken (2.4.C.1a)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8

2016-05-24 15:44

MOT test number

490685137485

Result**✓ Passed****MOT #7**

2016-05-24 08:43

MOT test number

802653932750

Result**✗ Failed****Fail**

Windscreen washer provides insufficient washer liquid (8.2.3)

Advice

Rear exhaust silencer corroded

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail

Offside Rear coil spring broken (2.4.C.1a)

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

Fail

Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

**MOT #6** 2015-06-09 12:09**MOT test number** 715330265114**Result** ✓ Passed**Notice** Rear exhaust silencer corroded**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Cut in offside rear tyre inner sidewall**MOT #5** 2015-06-09 09:21**MOT test number** 387610265101**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Rear exhaust silencer corroded**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Cut in offside rear tyre inner sidewall**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2014-06-17 15:42**MOT test number** 279388664425**Result** ✓ Passed**MOT #3** 2014-06-17 09:39**MOT test number** 306908364111**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Headlamp aim too low (1.8)**Notice** Items removed from driver's view prior to test



MOT #2	2013-09-03 15:59
MOT test number	295916343224
Result	✓ Passed
Notice	Fault with wipers

MOT #1	2013-09-03 11:02
MOT test number	946806043244
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
Fail	Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
Notice	Fault with wipers
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Notice	Oil level low
Fail	Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Notice	Coolant level low



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 August 2024

Tax status		Valid until 1 August
Days left		93
MOT expiry date		12 August 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-09-22
Last registration	2023-08-09
Complete history	See info



Registration #1	2010-09-22	27 mi
Registration #2	2013-09-03	21.981 mi
Registration #3	2013-09-03	21.982 mi
Registration #4	2014-06-17	32.385 mi
Registration #5	2014-06-17	32.385 mi
Registration #6	2015-06-09	41.876 mi
Registration #7	2015-06-09	41.876 mi
Registration #8	2016-05-24	51.181 mi
Registration #9	2016-05-24	51.181 mi
Registration #10	2017-06-15	56.993 mi
Registration #11	2017-06-15	56.993 mi
Registration #12	2018-06-15	62.805 mi
Registration #13	2018-06-15	62.805 mi
Registration #14	2019-06-15	68.617 mi
Registration #15	2019-06-15	68.617 mi
Registration #16	2020-06-15	74.429 mi
Registration #17	2020-06-15	74.429 mi
Registration #18	2021-06-15	80.241 mi
Registration #19	2021-06-15	80.241 mi
Registration #20	2022-06-15	86.053 mi
Registration #21	2022-06-15	86.053 mi
Registration #22	2023-08-09	91.865 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3674463