



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T3
Colour	Red
Year of manufacture	2006
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-11-05
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-02
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	32
Total items failed	16

MOT #22 2024-03-05 09:43

MOT test number 384644864863

Result ✓ Passed

Next expiry date 2025-04-02

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Front Headlamp lens slightly defective Both side (4.1.1 (b) (i))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #21 2023-04-03 15:51

MOT test number 522796509582

Result ✓ Passed

Advice Nearside Front Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #20**

2023-04-01 11:58

MOT test number

888563246013

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))**MOT #19**

2022-04-02 12:19

MOT test number

883444865220

Result**✓ Passed****Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #18**

2021-04-03 10:42

MOT test number

624420517827

Result**✓ Passed****Advice** Front Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))**MOT #17**

2020-06-27 14:43

MOT test number

469595015664

Result**✓ Passed**

**MOT #16** 2020-06-27 08:17**MOT test number** 770160974515**Result** ✗ Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15 2019-06-22 15:48**MOT test number** 504243778440**Result** ✓ Passed**MOT #14** 2019-06-22 09:55**MOT test number** 372641458619**Result** ✗ Failed

Fail Central Front Brake lever has insufficient reserve travel (1.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13 2018-06-22 08:54**MOT test number** 373384954262**Result** ✓ Passed

Advice Offside Rear position lamp 50% of light source illuminating

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #12**

2017-06-24 14:39

MOT test number

580266678280

Result

✓ Passed

Advice

Items removed from driver's view prior to test

Advice

Central Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11

2017-06-24 08:15

MOT test number

235629435959

Result

✗ Failed

Advice

Items removed from driver's view prior to test

Advice

Central Rear Child Seat fitted not allowing full inspection of adult belt

Fail

Front position lamp(s) not working (1.1.A.3b)

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail

Offside Rear Registration plate lamp not working (1.1.C.1d)

Fail

Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #10

2016-07-04 17:03

MOT test number

393983357859

Result

✓ Passed

**MOT #9** 2016-07-04 15:04**MOT test number** 725226911049**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-06-17 10:53**MOT test number** 639948865141**Result** ✓ Passed**MOT #7** 2014-06-25 10:23**MOT test number** 439286074131**Result** ✓ Passed**MOT #6** 2013-07-05 13:35**MOT test number** 207576383195**Result** ✓ Passed**MOT #5** 2012-07-05 10:35**MOT test number** 765827482186**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-06-08 14:31**MOT test number** 447169051117**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2011-06-08 14:31
MOT test number	169629951178
Result	✗ Failed
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Rear position lamp(s) not working (1.1.A.3b)
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)

MOT #2	2010-07-02 11:20
MOT test number	321773480139
Result	✓ Passed
Notice	Front wipers poor
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #1	2009-07-01 09:22
MOT test number	274772989133
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
2 April 2025

Tax status	Valid until 1 November
Days left	185
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-07-07
Last registration	2024-03-05
Complete history	See info



Registration #1	2006-07-07	7 mi
Registration #2	2009-07-01	59.664 mi
Registration #3	2010-07-02	65.146 mi
Registration #4	2011-06-08	72.632 mi
Registration #5	2012-07-05	80.027 mi
Registration #6	2013-07-05	84.421 mi
Registration #7	2014-06-25	88.756 mi
Registration #8	2015-06-17	96.799 mi
Registration #9	2016-07-04	103.957 mi
Registration #10	2016-07-04	103.957 mi
Registration #11	2017-06-24	109.206 mi
Registration #12	2017-06-24	109.206 mi
Registration #13	2018-06-24	115.206 mi
Registration #14	2019-06-24	121.206 mi
Registration #15	2020-06-24	127.206 mi
Registration #16	2021-06-24	133.206 mi
Registration #17	2022-06-24	139.206 mi
Registration #18	2023-06-24	145.206 mi
Registration #19	2024-03-05	151.206 mi
Registration #20	2024-03-05	151.206 mi
Registration #21	2024-03-05	151.206 mi
Registration #22	2024-03-05	151.206 mi
Registration #23	2024-03-05	151.206 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD5083493