





report date: 2024-03-28

### General information

Make	BMW
Model	218 218I M SPORT
Colour	Black
Year of manufacture	2018
Top speed	130 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	134 BHP	
Max. torque	220 Nm at 1.250 rpm	
Engine capacity	1.499 сс	
Cylinders	3	
Fuel type	Petrol	
Consumption city	40.9 mpg	
Consumption extra urban	58.9 mpg	
Consumption combined	52.3 mpg	
CO2 emission	130 g/km	
CO2 label	D	



CarCheck.co.uk page 1/12



NK18OCX report date: 2024-03-28


## Internet history


### Entry 1

Date 2021-10-28

Pictures 25

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

# MOT history

MOT expiry date	2025-02-04
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	21
Total items failed	7

MOT #9	2024-02-05 14:16
MOT test number	722803936189
Result	✓ Passed
Next expiry date	
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2024-02-03 11:27	
MOT test number	893595590106	
Result	<b>X</b> Failed	
Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))		

MOT #7	2023-02-02 14:09
MOT test number	266403999332
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #6** 2023-02-01 14:52

**MOT test number** 923123893493

Result X Failed

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #5 2022-10-13 15:41

MOT test number 996259807807

Result \( \sqrt{Passed} \)

**Advice** Screen scored

Minor Nearside Windscreen wiper blade defective grating (3.4 (b) (i))

**Advice** Shock absorbers has light misting of oil both front (5.3.2 (b))

MOT #4 2022-10-13 09:13

MOT test number 434046979857

Result X Failed

**Fail** Windscreen washer provides insufficient washer liquid both (3.5 (a))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**Advice** Shock absorbers has light misting of oil both front (5.3.2 (b))

**Advice** Screen scored

Minor Nearside Windscreen wiper blade defective grating (3.4 (b) (i))

MOT #3 2021-10-29 16:09

**MOT test number** 883466174603

Result \rightarrow Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

**MOT #2** 2021-03-02 15:33 **MOT** test number 202032346628 ✓ Passed Result **Advice** Rear Brake pad(s) wearing thin BOTH SIDES (1.1.13 (a) (ii)) **Advice** OFFSIDE REAR TYRE SIDEWALL PROTECTOR DISPLACED **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDES (1.1.14 (a) (ii)) Advice Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords SIDEWALL (5.2.3 (d) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #1** 2021-03-02 12:57 **MOT** test number 405449380674 Result **★** Failed **Advice** OFFSIDE REAR TYRE SIDEWALL PROTECTOR DISPLACED Fail Front Inner Brake pad(s) less than 1.5 mm thick BOTH SIDES (1.1.13 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords SIDEWALL (5.2.3 (d) (i)) Minor Brake fluid warning lamp illuminated (1.1.10 (f)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDES (1.1.14 (a) (ii)) **Advice** Rear Brake pad(s) wearing thin BOTH SIDES (1.1.13 (a) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	4 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

NK18OCX

report date: 2024-03-28

# For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-03-09
Last registration	2024-02-05
Complete history	See info



Registration #1	2018-03-09	24 mi
Registration #2	2021-03-02	43.258 mi
Registration #3	2021-03-02	43.258 mi
Registration #4		11.777 es
Registration #5	2021-10-29	48.260 mi
Registration #6	2022-10-13	56.312 mi
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		77.777 mg

More info >

CarCheck.co.uk page 11/12




report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1774 mm
Height	1418 mm
Length	4432 mm
Wheel base	2690 mm
Kerb weight	1340 kg
Max. allowed weight	1850 kg

# Additional information

Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number32945212