



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 DRIVE SE START/STOP
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-21
Pictures	12
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-07
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	30
Total items failed	1

MOT #12	2024-01-05 13:07
MOT test number	939821417828
Result	✓ Passed
Next expiry date	2025-01-07
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #11	2023-01-06 14:39
MOT test number	465588878065
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10	2022-01-07 11:40
MOT test number	747793068557
Result	✓ Passed

MOT #9	2021-01-08 09:47
MOT test number	146984786232
Result	✓ Passed

**MOT #8** 2021-01-05 14:23**MOT test number** 940596473698**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2020-05-27 10:44**MOT test number** 743870666917**Result** ✓ Passed**MOT #6** 2019-05-13 09:14**MOT test number** 303354653697**Result** ✓ Passed

**MOT #5** 2018-05-16 09:47**MOT test number** 522011266326**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Ball joint has slight play (2.2.B.1f)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2017-05-20 10:50**MOT test number** 111176376434**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-05-24 14:12**MOT test number** 722622760040**Result** ✓ Passed**Advice** Engine and underside covers fitted not allowing full inspection**Advice** Wipers smearing**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)

**MOT #2** 2016-05-19 14:51**MOT test number** 848160673454**Result** ✗ Failed

- Advice** N/s/f tyre has sidewall damage
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Engine and underside covers fitted not allowing full inspection
- Advice** Wipers smearing
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #1 2015-09-04 10:58**MOT test number** 216495098989**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-30
Last registration	2024-01-05
Complete history	See info



Registration #1	2012-03-30	9 mi
Registration #2	2015-09-04	32.484 mi
Registration #3	2016-05-19	38.343 mi
Registration #4	2016-05-24	38.344 mi
Registration #5	2017-05-20	64.004 mi
Registration #6	2018-05-16	80.293 mi
Registration #7	2019-05-13	87.903 mi
Registration #8	2020-05-20	95.513 mi
Registration #9	2021-05-20	103.123 mi
Registration #10	2022-05-20	110.733 mi
Registration #11	2023-05-20	118.343 mi
Registration #12	2024-01-05	125.953 mi
Registration #13	2024-01-05	125.953 mi
Registration #14	2024-01-05	125.953 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1582 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4130882