



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 5 STR
Colour	Black
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-28
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-10-03
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	40
Total items failed	6

## MOT #16 2023-09-29 14:33

MOT test number 788715393854

Result ✓ Passed

Next expiry date 2024-10-03

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen excessively tinted but not adversely affecting driver's view (3.2 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #15 2022-10-04 09:26

MOT test number 692359106375

Result ✓ Passed

- Minor** Front Anti-roll bar ball joint dust cover severely deteriorated ns and os (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement ns and os (5.3.4 (a) (i))
- Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated ns and os (5.3.4 (b) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement ns and os (5.3.4 (a) (i))

**MOT #14** 2021-08-14 08:53**MOT test number** 104815841736**Result** ✓ Passed**MOT #13** 2021-06-16 10:29**MOT test number** 449801556789**Result** ✗ Failed

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Central Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Central Rear Seat belt buckle damaged (7.1.2 (d))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12** 2020-02-13 10:25**MOT test number** 780684158078**Result** ✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2018-12-21 15:12**MOT test number** 119382638494**Result** ✓ Passed

**MOT #10**

2017-09-22 09:19

**MOT test number**

548292726715

**Result**

✓ Passed

**Advice**

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Offside Rear Seat belt damaged but webbing not significantly weakened middle row (5.2.2a)

**Advice**

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9**

2016-09-30 08:47

**MOT test number**

653112603629

**Result**

✓ Passed

**Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Child Seat fitted not allowing full inspection of adult belt Both Rear

**Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2015-10-02 10:29

**MOT test number**

526641574093

**Result**

✓ Passed

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR BUSH (2.4.G.2)

**Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR BUSH (2.4.G.2)

**MOT #7** 2014-09-26 15:57**MOT test number** 377679764468**Result** ✓ Passed

- Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Nearside rear bump stop broken
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2014-09-26 15:57**MOT test number** 199539764298**Result** ✗ Failed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nearside rear bump stop broken
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #5** 2013-09-06 16:22**MOT test number** 676809743244**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #4** 2013-09-05 10:42**MOT test number** 635218843219**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-09-19 12:27**MOT test number** 676143162273**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2011-09-28 10:25**MOT test number** 369571271250**Result** ✓ Passed**MOT #1** 2010-09-10 11:33**MOT test number** 163663350256**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
3 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	3 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>MA57BHX</b>
Plate since	2019-06-29
Current registration	<b>MA57BHX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-10-04
Last registration	2023-09-29
Complete history	<a href="#">See info</a>



Registration #1	2007-10-04	11 mi
Registration #2	2010-09-10	29.317 mi
Registration #3	2011-09-28	42.599 mi
Registration #4	2012-09-19	50.176 mi
Registration #5	2013-09-05	57.788 mi
Registration #6	2013-09-06	57.829 mi
Registration #7	2014-09-26	66.346 mi
Registration #8	2015-10-02	75.895 mi
Registration #9	2016-09-30	87.591 mi
Registration #10	2017-09-29	95.377 mi
Registration #11	2018-09-29	103.217 mi
Registration #12	2019-09-29	111.117 mi
Registration #13	2020-09-29	119.077 mi
Registration #14	2021-09-29	127.097 mi
Registration #15	2022-09-29	135.177 mi
Registration #16	2023-09-29	143.317 mi
Registration #17	2024-03-28	151.517 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD B25746