



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	CAPTUR DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Cream
Year of manufacture	2013
Top speed	106 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	20
Total items failed	15

MOT #14	2024-01-16 17:48
MOT test number	879546911903
Result	✓ Passed
Next expiry date	2025-02-01
Advice	Undertrays fitted, obscuring some components
Advice	Handbrake requires adjustment

MOT #13	2024-01-16 14:00
MOT test number	668012693614
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Handbrake requires adjustment
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))



MOT #12	2023-02-02 17:48
MOT test number	238534141391
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11	2023-02-02 14:56
MOT test number	822614812480
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #10	2022-03-04 17:09
MOT test number	570026876649
Result	✓ Passed
Advice	Undertray fitted
Advice	Nearside Front foglamp not working
Advice	Front radiator support corroded

**MOT #9** 2022-03-04 16:24**MOT test number** 859564411388**Result** ✗ Failed

- Advice** Front radiator support corroded
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2.3 (d) (ii))
- Advice** Undertray fitted
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking (205/55/17) (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm in places , bald on inner edge (5.2.3 (e))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front foglamp not working

MOT #8 2021-02-24 15:49**MOT test number** 177976391493**Result** ✓ Passed**MOT #7** 2020-11-05 12:57**MOT test number** 799725537178**Result** ✓ Passed

**MOT #6** 2020-10-26 10:57**MOT test number** 384699373912**Result** ✗ Failed

- Fail** Nearside Front Macpherson strut has an unsafe modification (5.3.3 (c) (i))
- Fail** Nearside Front Brake disc in such a condition that it is seriously weakened severely heat damaged (1.1.14 (a) (ii))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (ii))
- Fail** Offside Front Macpherson strut has an unsafe modification (5.3.3 (c) (i))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #5 2019-12-27 10:44**MOT test number** 516945296607**Result** ✓ Passed**MOT #4** 2018-12-17 15:24**MOT test number** 564832956918**Result** ✓ Passed**MOT #3** 2018-12-17 11:23**MOT test number** 607993865089**Result** ✗ Failed

- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #2 2017-12-23 09:39**MOT test number** 402405467097**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #1	2016-12-02 11:26
MOT test number	639080645201
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Front tyres worn on iside



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-12-30
Last registration	2024-01-16
Complete history	See info



Registration #1	2013-12-30	29 mi
Registration #2	2016-12-02	41.581 mi
Registration #3	2017-12-23	59.435 mi
Registration #4	2018-12-17	69.745 mi
Registration #5	2018-12-17	69.745 mi
Registration #6	2019-12-27	82.100 mi
Registration #7	2020-10-26	92.536 mi
Registration #8	2020-11-05	92.538 mi
Registration #9	2020-11-05	92.538 mi
Registration #10	2020-11-05	92.538 mi
Registration #11	2020-11-05	92.538 mi
Registration #12	2020-11-05	92.538 mi
Registration #13	2020-11-05	92.538 mi
Registration #14	2020-11-05	92.538 mi
Registration #15	2020-11-05	92.538 mi
Registration #16	2020-11-05	92.538 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1089 kg
Max. allowed weight	1663 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D021489