



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (60BHP)
Colour	Silver
Year of manufacture	2008
Top speed	97 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-02
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	28
Total items failed	10

MOT #18 2024-02-01 13:00

MOT test number 277032727847

Result ✓ Passed

Next expiry date 2025-02-02

- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #17 2023-02-03 15:44

MOT test number 616236197937

Result ✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16**

2023-01-13 15:53

MOT test number

438324865371

Result**✗ Failed**

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #15

2022-01-06 10:30

MOT test number

518463535451

Result**✓ Passed**

Advice Rear silencer outer skin badly corroded

Advice Front wheels nearside steel and offside alloy but same wheel and tyre size

MOT #14

2022-01-05 13:00

MOT test number

892232037851

Result**✗ Failed**

Advice Rear silencer outer skin badly corroded

Fail Anti-lock braking system warning lamp does not illuminate (1.6 (a))

Advice Front wheels nearside steel and offside alloy but same wheel and tyre size

MOT #13

2020-12-17 11:50

MOT test number

348738798801

Result**✓ Passed**

Advice Rear exhaust box skin extremely corroded

**MOT #12** 2020-12-11 18:04**MOT test number** 811928793709**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear exhaust box skin extremely corroded**MOT #11** 2020-10-05 08:51**MOT test number** 562753155524**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Exhaust box extremely corroded**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #10** 2019-12-06 12:39**MOT test number** 702194268278**Result** ✓ Passed**MOT #9** 2018-12-07 16:41**MOT test number** 183315355150**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Exhaust deteriorating.**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #8** 2017-12-18 13:29**MOT test number** 561989120146**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Engine and floor pan covers fitted.**Advice** Items removed from driver's view prior to test**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Exhaust deteriorating.**MOT #7** 2016-12-06 09:33**MOT test number** 207651794634**Result** ✓ Passed**MOT #6** 2016-12-06 09:33**MOT test number** 994647944914**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2015-12-08 10:15**MOT test number** 839653318165**Result** ✓ Passed**Advice** N/s/r tyre pershing**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2014-12-08 11:56
MOT test number	477142244489
Result	✓ Passed
<div>NoticeUnder-trays fitted obscuring some underside components</div>	
MOT #3	2013-12-23 14:09
MOT test number	298357453312
Result	✓ Passed
MOT #2	2012-12-19 12:13
MOT test number	495674852495
Result	✓ Passed
MOT #1	2011-12-16 10:07
MOT test number	445760951344
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KS58GWJ
Plate since	2019-03-29
Current registration	 KS58GWJ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-12-29
Last registration	2024-02-01
Complete history	See info



Registration #1	2008-12-29	28 mi
Registration #2	2011-12-16	16.791 mi
Registration #3	2012-12-19	24.129 mi
Registration #4	2013-12-23	30.488 mi
Registration #5	2014-12-08	38.292 mi
Registration #6	2015-12-08	47.484 mi
Registration #7	2016-12-06	51.554 mi
Registration #8	2016-12-06	51.554 mi
Registration #9	2017-12-18	54.661 mi
Registration #10	2018-12-07	56.610 mi
Registration #11	2019-05-29	58.557 mi
Registration #12	2019-05-29	58.557 mi
Registration #13	2019-05-29	58.557 mi
Registration #14	2019-05-29	58.557 mi
Registration #15	2019-05-29	58.557 mi
Registration #16	2019-05-29	58.557 mi
Registration #17	2019-05-29	58.557 mi
Registration #18	2019-05-29	58.557 mi
Registration #19	2019-05-29	58.557 mi
Registration #20	2019-05-29	58.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles

2

Engine number

BBM173167