





report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER P/U
Colour	Green
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	27.4 mpg



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1

Date 2022-04-15

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-04
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	45
Total items failed	21

MOT #19	2023-05-05 13:07
MOT test number	113173268011
Result	✓ Passed
Next expiry date	2024-05-04

MOT #18	2022-04-27 15:11
MOT test number	922359515582
Result	√ Passed

MOT #17		2021-07-26 14:58
MOT test	number	536661593385
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Replacement reco	ommended (5.2.3 (d)
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #16 2020-07-21 14:23 **MOT** test number 559943099612 ✓ Passed Result **Advice** Offside Rear tyre heavily perished + 3mm **Advice** Offside Seat belt slightly damaged (7.1.2 (b) (i)) Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Offside Front slight vertical play detected at wheel Advice Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Nearside mirror damaged Advice

MOT #15 2020-07-21 12:22 **MOT** test number 547337050767 Result × Failed **Advice** Nearside mirror damaged Nearside Rear Position lamp not working (4.2.1 (a) (ii)) Fail **Advice** Offside Rear tyre heavily perished + 3mm Fail Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii)) **Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Fail Stop lamp(s) all not working (4.3.1 (a) (iii)) Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Advice Offside Front slight vertical play detected at wheel Advice Offside Seat belt slightly damaged (7.1.2 (b) (i)) Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT test number

Result

Advice Rear Lower Shock absorbers has a slightly worn bush both (5.3.2 (c))

Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

Advice Offside Rear tyre heavily cracked / perished

MOT #13 2019-07-01 12:37 **MOT** test number 711940245524 Result × Failed Advice Rear Lower Shock absorbers has a slightly worn bush both (5.3.2 (c)) **Advice** Offside Rear tyre heavily cracked / perished Fail Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen jet missing (3.5(a))Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i)) **Minor** Registration plate lamp throwing direct white light to the rear (4.7.1 (a))

MOT #12 2018-06-20 15:57 **MOT** test number 637701448518 Result Passed **Advice** Nearside Rear Tyre slightly damaged/valve stem damaged valve heavily deteriorated (5.2.3 (d) (i)) Minor Registration plate lamp throwing direct white light to the rear (4.7.1 (a)) **Advice** Suspension component pin or bush slightly worn both rear lower shock absorber bushes (5.3.4 (a) (i)) Front Brakes imbalanced requirements only just met. It would appear that the braking system Advice requires adjustment or repair. (1.2.1 (b) (i))

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #11 2018-06-19 10:09

MOT test number 626023686562

Result X Failed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/valve stem damaged valve heavily deteriorated (5.2.3 (d) (i))

Fail Windscreen washer provides insufficient washer liquid jet broken (3.5 (a))

Fail Nearside Rear Position lamp not working (4.2.1 (a))

Advice Suspension component pin or bush slightly worn both rear lower shock absorber bushes (5.3.4 (a) (i))

MOT #10 2017-06-02 15:17

MOT test number 521130762153

Advice Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

MOT #9 2017-06-01 15:46

MOT test number 961196633369

Result × Failed

Advice Front wipers not tested

Advice Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Fail Windscreen washer provides insufficient washer liquid washer jet broken (8.2.3)

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT test number 690640820216

Result ✓ Passed

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)

Advice Offside Front tyre has small cracks in the side wall advise replacment

Advice Near side front tyre has small cracks in the side walls and tread advise replacment

MOT #7 2016-05-13 13:40 **MOT** test number 347530894429 Result × Failed Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Offside Rear Body has a sharp edge caused by damage reverse light lens broken (6.1.C.1) Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b) Fail Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Offside Front tyre has small cracks in the side wall advise replacment Advice **Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b) Fail Offside rear brake recording little or no effort (3.7.B.5a) Advice Near side front tyre has small cracks in the side walls and tread advise replacment Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4) Fail

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT #6

MOT test number

537866635078

Result

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Notice Both front tyres have small cracks on outer sidewalls

MOT #5 2015-02-05 09:54 **MOT** test number 697976635028 Result **X** Failed Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) **Notice** Both front tyres have small cracks on outer sidewalls **Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g) Fail Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)		
MOT #4	2014-01-24 10:02	
MOT test number	709894524097	
Result	✓ Passed	
MOT #3	2013-01-09 11:58	
MOT test number	337239403042	
Result	✓ Passed	

MOT #2	2012-01-31 15:16
MOT test number	597351832045
Result	✓ Passed

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #1

MOT test number

466438811065

Result


Notice Front bull bar damaged

CarCheck.co.uk page 9/16



PE57MUA report date: 2024-03-28

Tax & MOT check



CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.


Damage 1

Date
Category
Type

Damage 2
Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

$\hat{}$	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download	

	More info >
	More into >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	SIEZ ZIS UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-01-30
Last registration	2023-05-05
Complete history	See info



Registration #1	2008-01-30	24 mi
Registration #2	2011-01-18	29.429 mi
Registration #3	2012-01-31	37.396 mi
Registration #4	2013-01-09	46.061 mi
Registration #5	2014-01-24	50.514 mi
Registration #6	2015-02-05	51.965 mi
Registration #7	2015-02-05	51.965 mi
Registration #8	2016-05-13	54.645 mi
Registration #9	2016-05-14	54.649 mi
Registration #10	2017-06-01	56.333 mi
Registration #11	2017-06-02	56.333 mi
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		71.777 es
Registration #18		71.777 es
Registration #19		11.117 es
Registration #20		71.777 es
Registration #21		9.77 66

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Dimensions & weight

Width	1790 mm
Height	1968 mm
Length	3649 mm
Kerb weight	1705 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number	80510035842244D

CarCheck.co.uk page 16/16