




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO 2900 L2H1 CDTi P/V
Colour	Silver
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	49.5 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	H





MOT history

MOT expiry date	2025-02-05
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	10
Total items failed	5

MOT #7 2024-02-02 17:47

MOT test number 261040711992

Result ✓ Passed

Next expiry date 2025-02-05

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6 2024-02-02 15:14

MOT test number 765542782259

Result ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #5 2023-02-06 15:36

MOT test number 244305044970

Result ✓ Passed**Advice** Emission too clean

**MOT #4** 2021-11-26 19:27**MOT test number** 291349246178**Result** ✓ Passed**MOT #3** 2020-11-25 17:01**MOT test number** 646685472501**Result** ✓ Passed**MOT #2** 2020-11-25 10:08**MOT test number** 645993966838**Result** ✗ Failed**Fail** Offside Body component damaged and likely to cause injury MIRROR COVER (6.2.1 (a) (i))**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Central Seat belt retracting mechanism defective (7.1.2 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #1** 2019-10-24 14:53**MOT test number** 500048611607**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
5 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	5 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DK66NAA
Plate since	2019-03-29
Current registration	 DK66NAA
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-09-01
Last registration	2024-02-02
Complete history	See info



Registration #1	2016-09-01	10 mi
Registration #2	2019-10-24	27.728 mi
Registration #3	2020-11-25	36.826 mi
Registration #4	2020-11-25	36.826 mi
Registration #5	2022-05-20	36.826 mi
Registration #6	2022-05-20	36.826 mi
Registration #7	2022-05-20	36.826 mi
Registration #8	2024-02-02	36.826 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1710 kg
Max. allowed weight	2990 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MD - C141252LWZ