





report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Blue
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



CarCheck.co.uk page 1/11



DY58VMA report date: 2024-03-29

# Internet history

Emter.	1
Entry	т.

Elitiy 1	
Date	2022-02-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## **MOT** history

**MOT #14** 2021-08-18 14:45

**MOT test number** 189783830458

**Result** 
✓ Passed

Next expiry date 2022-08-19

**MOT #13** 2020-08-20 14:59

**MOT test number** 566064118087

**Result** 
✓ Passed

**Advice** Coil spring corroded Both Side Rear (5.3.1 (b) (i))

Minor Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12** 2019-08-19 08:51

**MOT test number** 530397491889

**Result** ✓ Passed

**MOT #11** 2019-08-16 15:13

**MOT test number** 635683120484

**Result** X Failed

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

(i))

**MOT #10** 2018-09-14 10:50

**MOT test number** 445098376837

**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #9

MOT test number

288202226895

Result

Advice Nearside Rear Rear wheel bearing has slight play (2.6.2)

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Exhaust has a minor leak of exhaust gases Fexi (7.1.2)

Advice Nearside Rear Rear wheel bearing has slight play (2.6.2)

 MOT #7
 2015-09-08 08:57

 MOT test number
 699078316629

 Result
 ✓ Passed

MOT #6

MOT test number

Result

Notice Front pipe of exhaust flexi broke but not blowing

2014-09-22 16:23

147315564277

✓ Passed

MOT test number

695125464222

Result

Fail Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Front pipe of exhaust flexi broke but not blowing

Fail Offside Rear Direction indicators incorrect colour (1.4.A.2f)

CarCheck.co.uk page 4/11



report date: 2024-03-29

2013-09-27 09:16

MOT test number 588650073244

**Result** ✓ Passed

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

MOT #4

**Advice** Brake pipe slightly corroded (3.6.B.2c)

**MOT #3** 2013-09-27 09:16

MOT test number 178010573244

**Result** X Failed

**Pass with rectification** Front Headlamp aim too low (1.8)

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

**Advice** Brake pipe slightly corroded (3.6.B.2c)

MOT #2 2012-10-01 11:57

MOT test number 899635472216

**Result** ✓ Passed

MOT #1 2011-10-21 09:30

**MOT test number** 328544191205

Result \rightarrow Passed

CarCheck.co.uk page 5/11



report date: 2024-03-29

## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

#### Damage 1

**Date Category Type** Damage 2

Category

**Type** 

**Date** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloahere.	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



DY58VMA report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-10-24
Last registration	2021-08-18
Complete history	See info



Registration #1	2008-10-24	18 mi
Registration #2	2011-10-21	40.119 mi
Registration #3	2012-10-01	52.898 mi
Registration #4	2013-09-27	65.560 mi
Registration #5	2014-09-22	80.009 mi
Registration #6	2014-09-22	80.009 mi
Registration #7	2015-09-08	97.279 mi
Registration #8	2016-09-08	103.342 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 esi
Registration #14		0.074

More info >

CarCheck.co.uk page 10/11



DY58VMA report date: 2024-03-29

Safety ratings

NCAP rating	****
-------------	------

**Video** <u>see crash video</u>



# Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

# Additional information

Fuel tank capacity	61
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564

CarCheck.co.uk page 11/11