



General information

Make	MINI
Model	MINI FIRST
Colour	White
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	140 Nm at 2.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 2

Date	2023-08-19
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-09-13
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	6

MOT #16	2023-08-24 11:06
MOT test number	395858861399
Result	✓ Passed
Next expiry date	2024-09-13
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #15	2022-09-05 12:04
MOT test number	902043427144
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-09-05 08:37
MOT test number	470433348376
Result	✗ Failed
MAJOR	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-09-14 14:14**MOT test number** 681546039468**Result** ✓ Passed**MOT #12** 2020-12-16 15:13**MOT test number** 641422748839**Result** ✓ Passed**MOT #11** 2020-06-24 08:13**MOT test number** 416917100302**Result** ✓ Passed**MOT #10** 2020-01-14 15:32**MOT test number** 559477921151**Result** ✓ Passed**MOT #9** 2019-01-15 08:55**MOT test number** 945177449846**Result** ✓ Passed**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**MOT #8** 2019-01-15 08:55**MOT test number** 327993651012**Result** ✗ Failed**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #7** 2018-01-16 09:35**MOT test number** 794128247040**Result** ✓ Passed

**MOT #6** 2017-07-20 13:12**MOT test number** 583478443501**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 175/65x15 (4.1.E.1)**Advice** Brake warning light illuminated**Advice** Nearside Rear Tyre worn close to the legal limit 175/65x15 (4.1.E.1)**MOT #5** 2017-07-20 13:12**MOT test number** 480793488157**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 175/65x15 (4.1.E.1)**Advice** Brake warning light illuminated**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit 175/65x15 (4.1.E.1)**MOT #4** 2016-08-09 09:53**MOT test number** 805104426569**Result** ✓ Passed**Advice** Offside Front tyre has cracks forming

**MOT #3** 2016-08-09 08:31**MOT test number** 452956268906**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front tyre has cracks forming**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2015-08-04 12:16**MOT test number** 835546315206**Result** ✓ Passed**MOT #1** 2014-08-15 15:38**MOT test number** 847937524245**Result** ✓ Passed



Tax & MOT check

✓

Taxed

Tax due:  
1 August 2024

✓

MOT

Expires:  
13 September 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	13 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-10-24
Last registration	2023-08-24
Complete history	<a href="#">See info</a>



Registration #1	2011-10-24	25 mi
Registration #2	2014-08-15	11.559 mi
Registration #3	2015-08-04	25.498 mi
Registration #4	2016-08-09	38.514 mi
Registration #5	2016-08-09	38.514 mi
Registration #6	2017-07-20	47.976 mi
Registration #7	2017-07-20	47.976 mi
Registration #8	2018-01-16	49.293 mi
Registration #9	2019-01-15	51.971 mi
Registration #10	2019-01-15	51.971 mi
Registration #11	2019-01-15	51.971 mi
Registration #12	2019-01-15	51.971 mi
Registration #13	2019-01-15	51.971 mi
Registration #14	2019-01-15	51.971 mi
Registration #15	2019-01-15	51.971 mi
Registration #16	2019-01-15	51.971 mi
Registration #17	2019-01-15	51.971 mi
Registration #18	2019-01-15	51.971 mi
Registration #19	2019-01-15	51.971 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	B626J063