





## General information

Make	ΤΟΥΟΤΑ
Model	AURIS
Colour	Red
Year of manufacture	2017
Top speed	111 mph
0 - 60 mph	11.2 seconds
Gearbox	1 speed CVT

## Engine & fuel consumption

Power	98 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	72.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	70.6 mpg
CO2 emission	92 g/km
CO2 label	А







Internet history		
Entry 1		
Date	2021-02-04	
Pictures	0	
Listing price	View report	

source: autoonline.co.uk



## MOT history

MOT expiry date	2025-03-31
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	33
Total items failed	4

МОТ #6	2024-03-20 10:30	
MOT test number	492671242524	
Result	✓ Passed	
Next expiry date	2025-03-31	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Inner rear (5.3.4 (a) (i))		
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)	)	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weake	ened (1.1.14 (a) (ii))	
Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely dete	eriorated (5.3.4 (b) (i))	





MOT #5 2024-03-20	09:36
MOT test number 7853277	53812
Result	Failed
<b>Advice</b> Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movemer Inner rear (5.3.4 (a) (i))	nt
Fail Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
<b>Fail</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i	))
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	





MOT #4	2023-03-23 09:27
MOT test n	humber 670578056112
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice rear bush (	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement 5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement 5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view small stone chips (3.2 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3	2022-	03-14 15:53
MOT test	: <b>number</b> 914	4283106260
Result		🗸 Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	dvice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))





🗸 Passed

MOT #2	2021-04-01 15:26
MOT test number	415887226003
Result	✓ Passed
Advice Front discs pitted	
Advice Rear discs pitted	
MOT #1	2020-03-06 14:42
MOT test number	118686260572

Result





Tax & MOT check

<b>Tax due:</b> 1 July 2024	✓ Taxed	<b>Expires:</b> 31 March 2025	✓ мот
Tax status			Valid until 1 July
Days left			62
MOT expiry date			31 March 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		59	

	55
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-31
Last registration	2024-03-20
Complete history	<u>See info</u>



Registration #1	2017-03-31	27 mi
Registration #2	2020-03-06	46.968 mi
Registration #3		11.777 mi
Registration #4	2021-04-01	47.263 mi
Registration #5		11.777 esi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		10.277 est





# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1760 mm
Height	1485 mm
Length	4595 mm
Wheel base	2600 mm
Kerb weight	1465 kg
Max. allowed weight	1865 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13