





report date: 2024-03-28

General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 2008 ACTIVE |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 105 mph |
| 0 - 60 mph | 13.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 82 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 114 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-01-22


Pictures 69

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-07-25 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 6 |
| Failed MOT tests | 3 |
| Total advice items | 24 |
| Total items failed | 0 |

| MOT #9 | 2023-07-26 14:52 |
|---|------------------|
| MOT test number | 609062604425 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-25 |
| Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) | |

| MOT #8 | | 2023-07-26 13:06 |
|---|---|------------------|
| MOT test | number | 323080582863 |
| Result | | X Failed |
| MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) | | |
| MAJOR Offside Rear fog lamp lens defective such that emitted light is adversely affected (4.5.1 (b) (ii)) | | |
| Minor | Battery insecure but not likely to fall from carrier (4.13 (a) (i)) | |

| MOT #7 | 2022-07-22 10:24 |
|--|------------------|
| MOT test number | 717919937706 |
| Result | ✓ Passed |
| Advice Exhaust mounting defective front pipe (6.1.2 (a)) | |

CarCheck.co.uk page 3/12



Result

Advice

KN65UGZ

report date: 2024-03-28

✓ Passed

 MOT #6
 2021-07-06 08:08

 MOT test number
 238224654314

Advice Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))

MOT #5 2020-11-20 07:54

MOT test number 896840176885

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))

MOT #4 2020-08-28 11:34

MOT test number 548127809622

Result

✓ Passed

MOT #3 2019-09-13 16:44

MOT test number 779660979349

Result \(\sqrt{Passed} \)

Advice Rear tyre tread cracking

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/12



KN65UGZ report date: 2024-03-28

MOT #2 2019-09-02 16:03

MOT test number 643387292666

Result

× Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened x2 brake discs wearing very thin (1.1.14 (a) (ii))

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing o/s/r and n/s/r tyres cracking tread area a lot (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin brake pads very low near. min for mot (1.1.13 (a) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Offside Front Headlamp aim not tested (4.1.2 (b))

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt inner cv boot insecure and leaking grease. metal clip missing (6.1.7 (g) (ii))

MOT #1 2018-09-03 08:59

MOT test number 107001267370

Result

× Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened x2 brake disc wearing thin (1.1.14 (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing o/s/r and n/s/r tyres started to cracking tread area (5.2.3 (d) (i))

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt inner cv boot insecure . clip missing (6.1.7 (g) (ii))

MAJOR Front Headlamp aim not tested o/s/f and n/s/f (4.1.2 (b))

MAJOR Front Headlamp not working on dipped beam o/s/f and n/s/f dipped beam inop (4.1.1 (a) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 64 |
| MOT expiry date | 25 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

KN65UGZ

report date: 2024-03-28

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2015-09-18 |
| Last registration | 2023-07-26 |
| Complete history | See info |



| Registration #1 | 2015-09-18 | 9 mi |
|------------------|------------|-----------|
| Registration #2 | 2018-09-03 | 25.356 mi |
| Registration #3 | 2019-09-02 | 38.241 mi |
| Registration #4 | 2019-09-13 | 38.636 mi |
| Registration #5 | 2020-08-28 | 51.471 mi |
| Registration #6 | 2020-11-20 | 52.664 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 0.074 |
| Registration #9 | | 0.074 |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 77% |
| Pedestrian | 72% |
| Safety systems | 70% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 2004 mm |
|---------------------|---------|
| Height | 1556 mm |
| Length | 4159 mm |
| Wheel base | 2538 mm |
| Kerb weight | 1210 kg |
| Max. allowed weight | 1582 kg |

Additional information

| Fuel tank capacity | 50 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

Number of axles 2

Engine number B2080342907