



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D S V50
Colour	Red
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-02
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-25
MOT pass rate	54 %
MOT passed	13
Failed MOT tests	11
Total advice items	44
Total items failed	28

MOT #24	2023-11-10 13:43
MOT test number	599725297728
Result	✓ Passed
Next expiry date	2024-11-25
Advice	Engine oil close to minimum

MOT #23	2023-11-08 10:59
MOT test number	677581321837
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Exhaust fumes causing a danger to health of persons on board (6.1.2 (b) (ii))
Advice	Engine oil close to minimum
Fail	Emissions unable to be completed Exhaust leak from under bonnet (8.2.2.2 (e))
Fail	Nearside Rear Anti-roll bar pin or bush likely to become detached (5.3.4 (a) (ii))

MOT #22	2022-11-09 14:32
MOT test number	566271794151
Result	✓ Passed
Advice	Exhaust deteriorated
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #21** 2022-10-27 15:11**MOT test number** 527442404271**Result** ✗ Failed**Advice** Exhaust deteriorated**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn Wishbone (5.3.4 (a) (i))**MOT #20** 2021-11-02 14:09**MOT test number** 314124578456**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement o/s & n/s trailing arm (5.3.4 (a) (i))**MOT #19** 2021-11-02 14:09**MOT test number** 293844940021**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement o/s & n/s trailing arm (5.3.4 (a) (i))**Pass with rectification** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #18** 2020-11-26 12:02**MOT test number** 426926985441**Result** ✓ Passed

**MOT #17**

2020-11-18 11:24

MOT test number

231494886100

Result**✗ Failed**

- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** N/s front and rear wheel bearings not tested due to brake bind
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Brake disc significantly and obviously worn brake pad metal to metal (1.1.14 (a) (i))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))

MOT #16

2019-10-16 11:05

MOT test number

546048018626

Result**✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs showing signs of surface rust (1.1.14 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #15

2019-10-16 11:05

MOT test number

909404412441

Result**✗ Failed**

- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs showing signs of surface rust (1.1.14 (a) (ii))

**MOT #14** 2018-07-09 13:03**MOT test number** 852239340183**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner faces (1.1.14 (a) (ii))

MOT #13 2018-07-09 08:47**MOT test number** 699858653360**Result** ✗ Failed

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner faces (1.1.14 (a) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #12 2017-07-20 15:59**MOT test number** 747256914706**Result** ✓ Passed

Advice Offside Front Inner Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Oil leak

MOT #11 2017-07-19 15:25**MOT test number** 495762113297**Result** ✗ Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Offside Front Inner Suspension arm has slight play in a ball joint (2.4.G.2)

Advice PARK BRAKE CABLE SNAPPED AFTER BRAKE TEST

Advice Oil leak

**MOT #10** 2016-07-12 16:23**MOT test number** 754510360863**Result** ✓ Passed**MOT #9** 2016-07-11 15:05**MOT test number** 975573740294**Result** ✗ Failed**Fail** Nearside Side repeater not working mirror indicator (1.4.A.2c)**MOT #8** 2015-08-14 10:33**MOT test number** 708554412105**Result** ✓ Passed**Advice** Nearside Rear Lower Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #7** 2015-08-13 12:21**MOT test number** 580879219283**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Nearside Rear Lower Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #6** 2014-08-13 14:01**MOT test number** 219875724298**Result** ✓ Passed**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #5	2013-08-21 10:05
MOT test number	376963733278
Result	✓ Passed

MOT #4	2012-08-22 16:37
MOT test number	258395532284
Result	✓ Passed
<div><div>Notice</div>Both front tyres wearing on shoulders , suggest having them changed</div> <div><div>Notice</div>Service light on</div>	

MOT #3	2012-08-22 14:53
MOT test number	409965432219
Result	✗ Failed
<div><div>Fail</div>Nearside Headlamp aim too far to the right (1.8)</div> <div><div>Notice</div>Both front tyres wearing on shoulders , suggest having them changed</div> <div><div>Fail</div>Offside Headlamp aim too low (1.8)</div> <div><div>Fail</div>Centre Upper Stop lamp not working (1.2.1b)</div> <div><div>Notice</div>Service light on</div>	

**MOT #2** 2011-09-02 16:54**MOT test number** 845775441274**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1 2011-09-02 10:38**MOT test number** 195875041237**Result** ✗ Failed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Headlamp aim too low (1.8)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

✓

MOT

Expires:
25 November 2024

Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	25 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SD58EPZ
Plate since	2024-03-29
Current registration	SD58EPZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2008-09-29
Last registration	2023-11-10
Complete history	See info



Registration #1	2008-09-29	7 mi
Registration #2	2011-09-02	35.857 mi
Registration #3	2011-09-02	35.858 mi
Registration #4	2012-08-22	50.982 mi
Registration #5	2012-08-22	50.983 mi
Registration #6	2013-08-21	62.576 mi
Registration #7	2014-08-13	71.824 mi
Registration #8	2015-08-13	80.518 mi
Registration #9	2015-08-14	80.519 mi
Registration #10	2016-07-11	88.244 mi
Registration #11	2016-07-12	88.244 mi
Registration #12	2017-07-19	110.232 mi
Registration #13	2017-07-20	110.236 mi
Registration #14	2018-05-29	121.277 mi
Registration #15	2018-05-29	121.277 mi
Registration #16	2018-05-29	121.277 mi
Registration #17	2018-05-29	121.277 mi
Registration #18	2018-05-29	121.277 mi
Registration #19	2018-05-29	121.277 mi
Registration #20	2018-05-29	121.277 mi
Registration #21	2018-05-29	121.277 mi
Registration #22	2018-05-29	121.277 mi
Registration #23	2018-05-29	121.277 mi
Registration #24	2018-05-29	121.277 mi
Registration #25	2018-05-29	121.277 mi
Registration #26	2018-05-29	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1436 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	421497