





report date: 2024-03-29

#### General information

| Make                | MINI             |
|---------------------|------------------|
| Model               | CLUBMAN COOPER D |
| Colour              | Green            |
| Year of manufacture | 2017             |
| Top speed           | 132 mph          |
| 0 - 60 mph          | 8.6 seconds      |
| Gearbox             | 6 speed Manual   |

#### Engine & fuel consumption

| Power                   | 150 BHP             |
|-------------------------|---------------------|
| Max. torque             | 330 Nm at 1.750 rpm |
| Engine capacity         | 1.995 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 55.4 mpg            |
| Consumption extra urban | 70.6 mpg            |
| Consumption combined    | 64.2 mpg            |
| CO2 emission            | 113 g/km            |
| CO2 label               | С                   |



CarCheck.co.uk page 1/10



Internet history

Entry 1

Date 2021-07-24

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date    | 2024-08-08 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 1          |
| Total advice items | 2          |
| Total items failed | 0          |

| MOT #5           | 2023-08-04 14:23 |
|------------------|------------------|
| MOT test number  | 259553639759     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-08-08       |

| MOT #4   |   | 2023-08-03 15:56 |
|----------|---|------------------|
| MOT test | number  | 809570056763     |
| Result   |   | <b>×</b> Failed  |
| MAJOR    | Central Rear Seat belt buckle not functioning as intended (7.1.2 (d)) |                  |

| MOT #3                           | 2022-08-06 10:08 |
|----------------------------------|------------------|
| MOT test number                  | 373232628149     |
| Result                           | <b>✓</b> Passed  |
| Advice Offside Rear Nail in tyre |                  |

| MOT #2          | 2021-08-09 08:38 |
|-----------------|------------------|
| MOT test number | 950966554443     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2020-09-17 10:02 |
| MOT test number | 398836432592     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/10



report date: 2024-03-29

#### Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 94                   |
| MOT expiry date  | 8 August 2024        |
| Full MOT history | See MOT history      |

#### Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | G          |
| First licence fee (12 months)                        | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

| Owner history  |             |
|--|-------------|
| For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here/">here</a> . |             |
| *********  |             |
| ***************************************  |             |
| ************   |             |
| ********   |             |
| ***************************************  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this MINI had different number plates.  |             |
| Number of plates   |             |
| Current registration   | NIE ZAIN UK |
| Plate since  | PR-0-0      |
| Current registration   | NK NY       |
| Plate since  |             |
|  | More info > |
|  |             |

CarCheck.co.uk page 7/10



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Courte at Info    |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

### Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2017-09-13 |
| Last registration          | 2023-08-04 |
| Complete history           | See info   |



| Registration #1 | 2017-09-13 | 24 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2020-09-17 | 42.609 mi |
| Registration #3 |            | 11.777 es |
| Registration #4 | 2021-08-09 | 44.346 mi |
| Registration #5 |            | 11.777 mi |
| Registration #6 |            | 11.777 es |
| Registration #7 |            | 11.777 no |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 90%             |
| Children       | 68%             |
| Pedestrian     | 68%             |
| Safety systems | 67%             |
| Overall rating | 77%             |
| Video          | see crash video |



### Dimensions & weight

| Width               | 2022 mm |
|---------------------|---------|
| Height              | 1441 mm |
| Length              | 4253 mm |
| Wheel base          | 2670 mm |
| Kerb weight         | 1395 kg |
| Max. allowed weight | 1910 kg |

# Additional information

| Fuel tank capacity                | 48 I             |
|-----------------------------------|------------------|
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 10/1      |