





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE SPORT TSI
Colour	Silver
Year of manufacture	2014
Top speed	129 mph
0 - 100 km/h	8.3 seconds
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 kW / 161 HP / 158 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2022-02-11

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-02-10

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-19
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	3

MOT #9		2024-04-10 16:16
MOT test	number	276295720695
Result		✓ Passed
Next expi	ry date	2025-04-19
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

MOT #8	2024-04-09 08:59
MOT test number	898277497520
Result	× Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Fail Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Fail Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2023-04-20 09:09

MOT test number 918218023523

Result ✓ Passed

Minor Offside Windscreen wiper blade defective slightly smeary (3.4 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

Rear bush (5.3.4 (a) (i))

Advice Rear Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

Rear bush (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Both rear tyres slightly misshapen on inner edges

MOT #6 2022-04-20 13:04

MOT test number 395132558540

Result
✓ Passed

Advice Tyre worn close to legal limit/worn on edge both front tyres worn (5.2.3 (e))

Advice Brake disc worn, pitted or scored, but not seriously weakened front brake discs inner faces edges

rusty (1.1.14 (a) (ii))

Advice Tyre slightly damaged/cracking or perishing front tyres small cracks in treads (5.2.3 (d) (ii))

MOT #5 2021-05-19 11:58

MOT test number 618374938472

Result \(\sqrt{Passed} \)

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2020-06-12 11:42

MOT test number 518729224008

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2019-04-29 14:53
MOT test number	485304735821
Result	✓ Passed
MOT #2	2018-05-09 15:11
MOT test number	431426268675
Result	✓ Passed
MOT #1	2017-11-16 11:50
MOT test number	478937863078
Result	✓ Passed

CarCheck.co.uk page 5/12



WR64YRY
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	19 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



-

WR64YRY

report date: 2024-03-28

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



WR64YRY report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-21
Last registration	2024-04-10
Complete history	See info



Registration #1	2014-11-21	18 mi
Registration #2	2017-11-16	11.989 mi
Registration #3	2018-05-09	14.793 mi
Registration #4	2019-04-29	18.423 mi
Registration #5	2020-06-12	25.881 mi
Registration #6	2021-05-19	26.786 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 au

More info >

CarCheck.co.uk page 11/12



WR64YRY report date: 2024-03-28

Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2021 mm
Height	1486 mm
Length	4278 mm
Wheel base	2537 mm
Kerb weight	1359 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
CarChack caluk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	CTHD126254