



WF58RZH

report date: 2024-03-29

General information

Make	MAZDA
Model	3 TAMURA
Colour	Blue
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg





MOT history

MOT #16 2023-09-19 14:26

MOT test number 658942607775

Result ✓ Passed

Next expiry date 2024-09-18

- Advice** Nearside Front Lower Suspension arm ball joint has slight play On the limit (5.3.4 (a) (i))
- Advice** Nearside outer sill has slight damage the section where the rear door is fouling the sill but structural rigidity is not significantly reduced
- Advice** Rear Brake hose has slight corrosion to ferrule Nearside and Offside (1.1.12 (f) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing Nearside and Offside (5.2.3 (d) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Rear exhaust system slightly deteriorated

**MOT #15**

2023-09-11 12:05

MOT test number

914916511128

Result**✗ Failed**

Advice Offside Front Tyre worn close to legal limit/worn on edge On the limit -1.6mm of tyre tread (5.2.3 (e))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside outer sill has slight damage the section where the rear door is fouling the sill but structural rigidity is not significantly reduced

Advice Front Tyre slightly damaged/cracking or perishing Nearside and Offside (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm ball joint has slight play On the limit (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2-3mm of tyre tread (5.2.3 (e))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Rear Brake hose has slight corrosion to ferrule Nearside and Offside (1.1.12 (f) (i))

Advice Rear exhaust system slightly deteriorated

Advice Front Registration plate insecure but not likely to fall off (0.1 (a))

Advice Rear Tyre slightly damaged/cracking or perishing Nearside and Offside (5.2.3 (d) (ii))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #14

2022-09-12 10:05

MOT test number

969716843333

Result**✓ Passed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

**MOT #13** 2021-09-08 11:02**MOT test number** 142541514416**Result** ✓ Passed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #12** 2021-09-08 11:02**MOT test number** 236494939443**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #11** 2020-08-14 12:15**MOT test number** 995340441430**Result** ✓ Passed**MOT #10** 2019-09-30 14:21**MOT test number** 137025557500**Result** ✓ Passed

**MOT #9** 2019-07-22 09:50**MOT test number** 498561089648**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2018-07-25 08:33**MOT test number** 620387972796**Result** ✓ Passed**MOT #7** 2017-08-17 14:39**MOT test number** 435067642913**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2016-08-12 12:08**MOT test number** 587811427577**Result** ✓ Passed

**MOT #5** 2015-09-15 11:46**MOT test number** 145061376380**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2014-09-18 15:04**MOT test number** 979801764247**Result** ✓ Passed**MOT #3** 2013-09-12 12:56**MOT test number** 377945753459**Result** ✓ Passed**MOT #2** 2012-09-13 10:11**MOT test number** 988877852293**Result** ✓ Passed**MOT #1** 2011-09-13 16:06**MOT test number** 117996951219**Result** ✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	WF58RZH
Plate since	2024-03-29
Current registration	WF58RZH
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-10-30
Last registration	2023-09-19
Complete history	See info



Registration #1	2008-10-30	28 mi
Registration #2	2011-09-13	4.599 mi
Registration #3	2012-09-13	6.318 mi
Registration #4	2013-09-12	7.741 mi
Registration #5	2014-09-18	7.996 mi
Registration #6	2015-09-15	8.324 mi
Registration #7	2016-08-12	8.593 mi
Registration #8	2017-08-17	15.779 mi
Registration #9	2018-07-25	19.147 mi
Registration #10	2019-09-20	20.277 mi
Registration #11	2020-09-20	20.277 mi
Registration #12	2021-09-20	20.277 mi
Registration #13	2022-09-20	20.277 mi
Registration #14	2023-09-20	20.277 mi
Registration #15	2024-09-20	20.277 mi
Registration #16	2025-09-20	20.277 mi
Registration #17	2026-09-20	20.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4420 mm
Wheel base	2640 mm
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z6652749