



BD06ZNJ

report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA
Colour	Grey
Year of manufacture	2006
Gearbox	-

Engine & fuel consumption

Engine capacity	1.497 cc
Fuel type	Petrol
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-22
Pictures	10
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-08-31
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	31
Total items failed	6

MOT #18 2023-08-16 08:24**MOT test number** 111584855088**Result** Passed**Next expiry date** 2024-08-31

- Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))

MOT #17 2022-09-01 13:06**MOT test number** 786866015182**Result** Passed

- Advice** Suspension component corroded but not seriously weakened All front and rear (5.3.3 (b) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))
- Advice** Front Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))

**MOT #16**

2022-09-01 13:06

MOT test number

525915538906

Result**✗ Failed****Advice**

Front Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))

Advice

Front Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))

Pass with rectification

Nearside Front Headlamp aim too high (4.1.2 (a))

Advice

Suspension component corroded but not seriously weakened All front and rear (5.3.3 (b) (i))

Advice

Rear Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))

Advice

Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))

Pass with rectification

Offside Front Headlamp aim too high (4.1.2 (a))

MOT #15

2021-08-31 12:49

MOT test number

786777109093

Result**✓ Passed****Advice**

Nearside Front Brake pipe corroded, covered in grease or other material and offside front brake pipes have been greased (1.1.11 (c))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material and offside rear brake pipes have been greased (1.1.11 (c))

MOT #14

2020-08-06 08:09

MOT test number

767395780305

Result**✓ Passed****Advice**

O/s front brake sticking slightly

Advice

Front number plate peeling

Advice

Rear tyres worn/cracking

**MOT #13** 2019-07-29 11:54**MOT test number** 856064436886**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-07-24 09:14**MOT test number** 171918185689**Result** ✓ Passed**MOT #11** 2017-08-10 08:03**MOT test number** 387245147074**Result** ✓ Passed**Advice** Keep check on o/s rear tyre depth**MOT #10** 2016-08-09 07:52**MOT test number** 634056010786**Result** ✓ Passed**Advice** Keep check on o/s rear tyre depth-under 2.5mm**MOT #9** 2015-07-20 10:08**MOT test number** 205181605231**Result** ✓ Passed**MOT #8** 2014-07-28 11:53**MOT test number** 299489104277**Result** ✓ Passed

**MOT #7** 2013-08-05 10:03**MOT test number** 289217413270**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #6** 2012-07-25 12:45**MOT test number** 388657602250**Result** ✓ Passed**MOT #5** 2012-07-25 12:45**MOT test number** 436867402224**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2011-08-05 15:18**MOT test number** 278347511280**Result** ✓ Passed**MOT #3** 2010-08-05 12:54**MOT test number** 602027410202**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** ALL BRAKE DISCS ARE IN A RUSTY CONDITION**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #2	2010-08-05 12:54
MOT test number	383747710286
Result	✓ Passed
Notice	ALL BRAKE DISCS ARE IN A RUSTY CONDITION
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1	2009-06-24 14:31
MOT test number	651965179137
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-06-30
Last registration	2023-08-16
Complete history	See info



Registration #1	2006-06-30	24 mi
Registration #2	2009-06-24	7.357 mi
Registration #3	2010-08-05	9.396 mi
Registration #4	2011-08-05	12.120 mi
Registration #5	2012-07-25	16.250 mi
Registration #6	2013-08-05	20.123 mi
Registration #7	2014-07-28	23.142 mi
Registration #8	2015-07-20	27.975 mi
Registration #9	2016-08-09	31.708 mi
Registration #10	2016-08-09	31.708 mi
Registration #11	2016-08-09	31.708 mi
Registration #12	2016-08-09	31.708 mi
Registration #13	2016-08-09	31.708 mi
Registration #14	2016-08-09	31.708 mi
Registration #15	2016-08-09	31.708 mi
Registration #16	2016-08-09	31.708 mi
Registration #17	2016-08-09	31.708 mi
Registration #18	2016-08-09	31.708 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Engine number GA16-566159