



report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Blue
Year of manufacture	2001
Top speed	143 mph
0 - 60 mph	7.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	284 Nm at 3.000 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.7 mpg
Consumption extra urban	36.4 mpg
Consumption combined	27.0 mpg
CO2 emission	249 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-07-13
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-15
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	54
Total items failed	16

MOT #22	2024-02-16 12:32
MOT test number	890860743856
Result	✓ Passed
Next expiry date	2025-02-15

MOT #21	2023-02-02 17:24
MOT test number	859347330088
Result	✓ Passed

MOT #20	2020-09-21 14:47
MOT test number	808612505759
Result	✓ Passed

MOT #19	2020-09-15 14:44
MOT test number	399737897297
Result	✗ Failed

**Fail** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

MOT #18	2019-09-27 15:31
MOT test number	962113060600
Result	✓ Passed

**MOT #17**

2019-09-14 09:50

**MOT test number**

361647489129

**Result**

✗ Failed

**Fail**

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Fail**

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #16**

2018-11-23 17:33

**MOT test number**

199720198800

**Result**

✗ Failed

**Fail**

Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

**Fail**

Offside Front Brake hose excessively damaged (1.1.12 (b) (ii))

**Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail**

Offside Headlamp aim too low and too far to the right. (4.1.2 (a))

**Fail**

Offside Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

**Advice**

Front Brake pipe corroded, covered in grease or other material to rears (1.1.11 (c))

**Advice**

Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

**MOT #15**

2016-11-18 14:37

**MOT test number**

244240581929

**Result**

✓ Passed

**Advice**

Engine warning light on



MOT #14

2015-05-06 13:19

MOT test number

519866525100

Result		✓ Passed
Notice	Nearside rear tyre perished	
Notice	Engine management warning lamp remains illuminated	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Brake fluid low level	
Advice	Offside Outer Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Nearside sill corroded	
Notice	Both rear anti roll bar/body bushes worn	
Notice	Nail in offside rear tyre	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Drivers seatbelt webbing damaged	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Coolent leak	
Notice	Nearside rear brake pipe corroded	

**MOT #13**

2015-05-06 13:19

**MOT test number**

828446825113

**Result****✗ Failed**

- Notice** Nearside sill corroded
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Both rear anti roll bar/body bushes worn
- Notice** Nail in offside rear tyre
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Drivers seatbelt webbing damaged
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Coolant leak
- Notice** Nearside rear brake pipe corroded
- Advice** Offside Outer Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Nearside rear tyre perished
- Notice** Engine management warning lamp remains illuminated
- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Notice** Brake fluid low level

**MOT #12**

2013-06-25 16:31

**MOT test number**

458126073127

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2013-06-25 16:25

**MOT test number**

237986673180

**Result**

✗ Failed

**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #10**

2012-04-13 15:41

**MOT test number**

398034602197

**Result**

✓ Passed

**Notice** Both rear coil springs corroded**Advice** Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Notice** Air bag warning lamp on**MOT #9**

2011-06-13 12:52

**MOT test number**

335934261127

**Result**

✓ Passed

**Notice** Corrosion on rear coil springs**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8**

2010-05-11 17:11

**MOT test number**

234621130196

**Result**

✓ Passed

**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Brake pipe slightly chafed (3.6.B.2c)

**MOT #7** 2010-04-28 12:39**MOT test number** 843788810166**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Front Brake pipe slightly chafed (3.6.B.2c)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2009-04-30 12:20**MOT test number** 282660629104**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-04-27 15:07**MOT test number** 722107019155**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear position lamp(s) excessively damaged so that it is not visible from a reasonable distance (1.1.A.3d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc slightly pitted (3.5.1h)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



**MOT #4** 2007-07-25 16:46**MOT test number** 270596107256**Result** ✓ Passed

**Advice** Front Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #3** 2006-07-25 09:44**MOT test number** 113396606296**Result** ✓ Passed**MOT #2** 2006-07-25 09:44**MOT test number** 130526006261**Result** ✗ Failed

**Pass with rectification** Offside Outer Headlamp aim beam image too far to the right (1.6.B4)

**Pass with rectification** Nearside Outer Headlamp aim beam image too far to the right (1.6.B4)

**MOT #1** 2005-07-25 15:05**MOT test number** 350946205404**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
15 February 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	15 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>Y102NVX</b>
Plate since	2024-03-28
Current registration	<b>Y102NVX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2001-07-26
Last registration	2024-02-16
Complete history	<a href="#">See info</a>



Registration #1	2001-07-26	26 mi
Registration #2	2005-07-25	31.026 mi
Registration #3	2006-07-25	32.071 mi
Registration #4	2007-07-25	33.542 mi
Registration #5	2009-04-27	33.608 mi
Registration #6	2009-04-30	33.608 mi
Registration #7	2010-04-28	36.755 mi
Registration #8	2010-05-11	36.798 mi
Registration #9	2011-06-13	40.148 mi
Registration #10	2012-04-13	41.984 mi
Registration #11	2013-06-25	51.466 mi
Registration #12	2014-06-25	51.466 mi
Registration #13	2015-06-25	51.466 mi
Registration #14	2016-06-25	51.466 mi
Registration #15	2017-06-25	51.466 mi
Registration #16	2018-06-25	51.466 mi
Registration #17	2019-06-25	51.466 mi
Registration #18	2020-06-25	51.466 mi
Registration #19	2021-06-25	51.466 mi
Registration #20	2022-06-25	51.466 mi
Registration #21	2023-06-25	51.466 mi
Registration #22	2024-02-16	51.466 mi

More info >



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	177392401WB