





report date: 2024-03-28

#### General information

Make	HYUNDAI
Model	I10 SE
Colour	White
Year of manufacture	2018
Top speed	97 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	50.4 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

### Internet history

#### Entry 1

Date 2021-09-20

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

MOT expiry date	2024-06-04
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #4		2023-06-05 10:16
MOT test	number	237412928457
Result		<b>✓</b> Passed
Next expi	ry date	2024-06-04
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2023-06-05 10:16
MOT test number	894753233758
Result	<b>x</b> Failed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass with rectification Nearside Daytime running lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2		2022-06-13 12:00
MOT test	number	643742963367
Result		<b>✓</b> Passed
Advice	Tyre slightly damaged/cracking or perishing all tyres perished osf of	osr nsf nsr (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-07-06 14:53

**MOT test number** 428042475897

**Result** ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	4 June 2024
Full MOT history	See MOT history

#### Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
---------------	--

e when motory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
*******	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-08-13
Last registration	2023-06-05
Complete history	See info



Registration #1	2018-08-13	19 mi
Registration #2	2021-07-06	11.075 mi
Registration #3		11.777 46
Registration #4		11.777 es
Registration #5		11.777 es
Devictor #C		

Registration #6

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

# Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	933 kg
Max. allowed weight	1420 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles2Engine numberG3LAJD070635