





report date: 2024-03-29

General information

Make	BMW
Model	530 530I SPORT
Colour	Black
Year of manufacture	2003
Top speed	152 mph
0 - 60 mph	7.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.500 rpm
Engine capacity	2.979 сс
Cylinders	6
Fuel type	Petrol
Consumption city	18.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	26.4 mpg
CO2 emission	257 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-05

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-11
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	24
Total items failed	6

MOT #13		2024-01-12 12:42
MOT test	number	329218142129
Result		✓ Passed
Next exp	iry date	2025-01-11
Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #12	2022-12-10 08:41
MOT test number	742074429694
Result	✓ Passed
MOT #11	2021-05-21 09:19
MOT test number	458994887721
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10 2021-05-15 10:45

MOT test number 680659157982

Result X Failed

MAJOR Offside Headlamp aim too low (4.1.2 (a))

MAJOR Nearside Front Service brake excessively binding (1.2.1 (f))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9 2013-08-15 14:55

MOT test number 329597423439

Result

Passed

Advice Nearside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A'

(8.3.1d)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #8 2013-08-14 11:24

MOT test number 905526723281

Result X Failed

Advice Nearside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail Offside Rear Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Parking brake lever has no reserve travel (3.1.6b)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Fail Nearside Rear Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Offside Rear Tie bar/rod has slight play in a pin/bush (2.4.G.2)

CarCheck.co.uk page 4/13



Advice

HT03OAV

report date: 2024-03-29

MOT test number

Result

Advice (8.3.1d)

Notice Child seat fitted not allowing full inspection of adult belt

Offside Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #6

MOT test number

Result

Advice (8.3.1d)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT test number

Fail

Offside Rear Lower Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #4

MOT test number

Result

Notice Nail in offside front tyre

Pass with rectification Horn not working (1.6.2a)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3	2010-08-16 12:32
MOT test number	233928820241
Result	✓ Passed
Notice Nail in offside front tyre	

Notice Nail in offside front tyre		
MOT #2		2007 00 11 17 20
MOT #2 MOT test	number	2007-09-11 17:20 542274157285
Result		✓ Passed
MOT #1		2006-06-09 10:08
MOT test	number	910450866148
Result		√ Passed
Advice	Nearside Inner Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	
Notice	Damage offside undershield.	
Advice	Offside Inner Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
STREET, STREET	
2000000	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



HT03OAV report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2003-06-30
Last registration	2024-01-12
Complete history	See info



Registration #1	2003-06-30	20 mi
Registration #2	2006-06-09	71.402 mi
Registration #3	2007-09-11	115.929 mi
Registration #4	2010-08-16	94.009 mi
Registration #5	2011-08-11	100.267 mi
Registration #6	2011-08-11	100.267 mi
Registration #7	2012-07-31	105.296 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1435 mm
Length	4775 mm
Wheel base	1558 mm

Additional information

Fuel tank capacity	70 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	31652940

CarCheck.co.uk page 13/13