



**BD6IWLW**

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Blue
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-07-16
Pictures	21
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-23
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #12	2024-03-13 11:19
MOT test number	888349991775
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11	2023-03-14 16:41
MOT test number	720518485196
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2023-03-14 12:28

**MOT test number**

388254898946

**Result****✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9**

2022-03-23 16:50

**MOT test number**

613321988791

**Result****✓ Passed****Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8**

2021-03-01 16:19

**MOT test number**

571866893269

**Result****✓ Passed****Advice** Rear number plate getting delaminated**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7**

2020-02-25 14:19

**MOT test number**

550658968147

**Result****✓ Passed****Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge starting to wear on inner edge (5.2.3 (e))

**MOT #6** 2019-03-19 14:58**MOT test number** 797032096991**Result** ✓ Passed**MOT #5** 2018-03-08 14:18**MOT test number** 331992390869**Result** ✓ Passed**Advice** Rear brake discs heavily corroded**MOT #4** 2017-03-20 15:24**MOT test number** 708532497423**Result** ✓ Passed**MOT #3** 2016-03-24 15:45**MOT test number** 151412099158**Result** ✓ Passed**Advice** Rear brake disc modified but not seriously weakened (3.5.1n)**Advice** Front tyres wearing on inner edges**MOT #2** 2016-03-24 12:05**MOT test number** 852195547291**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front tyres wearing on inner edges**Advice** Rear brake disc modified but not seriously weakened (3.5.1n)**MOT #1** 2015-01-12 12:31**MOT test number** 888152515092**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-01-12
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2012-01-12	6 mi
Registration #2	2015-01-12	26.522 mi
Registration #3	2016-03-24	39.899 mi
Registration #4	2016-03-24	39.899 mi
Registration #5	2017-03-20	54.083 mi
Registration #6	2018-03-08	70.521 mi
Registration #7	2019-03-19	88.571 mi
Registration #8	2020-03-20	106.621 mi
Registration #9	2021-03-20	124.671 mi
Registration #10	2022-03-20	142.721 mi
Registration #11	2023-03-20	160.771 mi
Registration #12	2024-03-13	178.821 mi
Registration #13	2024-03-13	178.821 mi
Registration #14	2024-03-13	178.821 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAYCK90899