





### General information

Make	PEUGEOT
Model	HORIZON E-HDI TEPEE S
Colour	Bronze
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	58.9 mpg





### Internet history

Entry 1

Date Pictures 2021-01-21

27

Listing price

View report



source: yesauto.com



# MOT history

MOT expiry date	2024-06-24
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	7
Total items failed	10

MOT #13	2023-06-19 08:45
MOT test number	171856281135
Result	🗸 Passed
Next expiry date	2024-06-24
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #12	2022-06-13 08:58
MOT test number	407526031572
Result	✓ Passed
MOT #11	2021-06-23 10.21

	2021-00-23 10.21
MOT test number	499630270761
Result	✓ Passed





MOT #	<b>10</b> 2021-06-21 10:3	0
MOT te	st number 54793978616	3
Result	× Faile	d
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #9	2020-06-25 14:50
MOT test number	102748379090
Result	✓ Passed

MOT #8	2020-03-25 15:19
MOT test number	517967278673
Result	🗙 Failed
<b>Fail</b> Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #7	2019-04-01 09:00
MOT test number	187686078401
Result	✓ Passed

MOT #6	2018-11-10 12:58
MOT test number	932274610853
Result	✓ Passed





MOT #5	2018-04-06 16:21
MOT test number	961879706722
Result	✓ Passed
Advice Front Windscreen has damage to an area less than a 10mm circle within zone	A' (8.3.1a)
MOT #4	2018-04-06 16:21
MOT #4 MOT test number	2018-04-06 16:21 985577623987
MOT test number	985577623987 🗙 Failed

MOT #3		2017-04-25 15:37
MOT test	number	682661976689
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Engine cover and under tray fitted unable to check all components	

MOT #2	2017-04-25 15:37	
MOT test number	156992928580	
Result	🗙 Failed	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)		
Advice Engine cover and under tray fitted unable to check all components		
Pass with rectification Central Stop lamp not working (1.2.1b)		

MOT #1	2016-05-09 13:32
MOT test number	911052807001
Result	✓ Passed



Tax & MOT check







#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plata since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-06-10
Last registration	2023-06-19
Complete history	<u>See info</u>



Registration #1	2013-06-10	29 mi
Registration #2	2016-05-09	30.257 mi
Registration #3	2017-04-25	58.086 mi
Registration #4	2017-04-25	58.086 mi
Registration #5	2018-04-06	53.648 mi
Registration #6	2018-04-06	53.648 mi
Registration #7	2018-11-10	59.149 mi
Registration #8	2019-04-01	59.179 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 mi





#### Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
S0567	
S0569	

## Safety ratings

Number of doors

Number of seats

Number of axles CarCheck.co.uk

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2112 mm
Height	1862 mm
Length	4380 mm
Wheel base	2728 mm
Max. allowed weight	2070 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection

5

5

2

**Engine number** 

JBFR3005683