



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Grey
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-09-01
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	43
Total items failed	23

MOT #21	2023-08-19 07:53
MOT test number	459717244403
Result	✓ Passed
Next expiry date	2024-09-01
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2023-08-12 10:02

MOT test number

506433016363

Result

✗ Failed

Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust emissions likely to be affected by an exhaust leak flexi (8.2.1.1 (b))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**MOT #19**

2022-08-13 15:17

MOT test number

527871650861

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #18**

2022-08-06 10:19

MOT test number

492233218497

Result

✗ Failed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Driver's door cannot be opened from inside the vehicle (6.2.3 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #17** 2021-09-02 09:22**MOT test number** 538171880746**Result** ✓ Passed**MOT #16** 2021-09-01 14:24**MOT test number** 548101944886**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #15** 2020-10-24 14:56**MOT test number** 262774835439**Result** ✗ Failed**Advice** Offside Rear Tyre is cracking/deteriorated**Advice** Offside Front Tyre is worn on edges**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Nearside Rear Tyre is cracking/deteriorated**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre has damage to sidewall suspect tyre has been run flat**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Parking brake lever has very little reserve travel**Fail** Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #14**

2019-11-09 12:56

MOT test number

813204103211

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3MM Remaining, Cracking, Perishing (195/55R15 (5.2.3 (e)))

Minor Nearside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3MM Remaining, Cracking, Perishing (195/55R15 (5.2.3 (e)))

Advice Nearside Front Play in steering rack inner joint(s)

Minor Offside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Sump Corroded

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13

2019-11-09 10:53

MOT test number

308262289787

Result

✗ Failed

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Sump Corroded

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3MM Remaining, Cracking, Perishing (195/55R15 (5.2.3 (e)))

Minor Offside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3MM Remaining, Cracking, Perishing (195/55R15 (5.2.3 (e)))

Minor Nearside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Nearside Front Play in steering rack inner joint(s)

**MOT #12** 2018-11-05 10:28**MOT test number** 516271119443**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2018-11-05 10:07**MOT test number** 948223773773**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #10** 2017-10-28 15:40**MOT test number** 822080443623**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases flexi (7.1.2)**MOT #9** 2017-10-28 09:24**MOT test number** 323210842030**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Front Exhaust has a minor leak of exhaust gases flexi (7.1.2)**Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #8** 2016-10-29 08:28**MOT test number** 223803304454**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Nail in tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-11-07 12:37**MOT test number** 662976971522**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Under-trays fitted obscuring some underside components**MOT #6** 2014-11-25 12:06**MOT test number** 989499124382**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-11-22 14:06**MOT test number** 419726823446**Result** ✓ Passed**MOT #4** 2013-11-22 14:06**MOT test number** 308666623307**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)



MOT #3	2012-12-01 10:57
MOT test number	625516632398
Result	✓ Passed
Advice	Offside Front front brake juddering slightly (3.7.A.2b)

MOT #2	2011-12-30 10:19
MOT test number	486664761356
Result	✓ Passed

MOT #1	2011-09-15 18:04
MOT test number	329328051230
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXX
Plate since	2024-03-28
Current registration	 XXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-13
Last registration	2023-08-19
Complete history	See info



Registration #1	2008-10-13	9 mi
Registration #2	2011-09-15	28.455 mi
Registration #3	2011-12-30	28.479 mi
Registration #4	2012-12-01	35.001 mi
Registration #5	2013-11-22	42.752 mi
Registration #6	2014-11-25	53.167 mi
Registration #7	2015-11-07	62.408 mi
Registration #8	2016-10-29	71.519 mi
Registration #9	2017-10-28	76.823 mi
Registration #10	2017-10-28	76.823 mi
Registration #11	2018-11-05	83.788 mi
Registration #12	2019-05-20	91.277 mi
Registration #13	2019-05-20	91.277 mi
Registration #14	2019-05-20	91.277 mi
Registration #15	2019-05-20	91.277 mi
Registration #16	2019-05-20	91.277 mi
Registration #17	2019-05-20	91.277 mi
Registration #18	2019-05-20	91.277 mi
Registration #19	2019-05-20	91.277 mi
Registration #20	2019-05-20	91.277 mi
Registration #21	2019-05-20	91.277 mi
Registration #22	2023-08-19	91.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BUD538829