



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE FAP DCI 130 SCENIC
Colour	Black
Year of manufacture	2007
Top speed	119 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	39.8 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-05
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	47
Total items failed	29

MOT #23	2024-01-31 09:20
MOT test number	231050021356
Result	✓ Passed
Next expiry date	2025-01-30

MOT #22	2022-12-06 12:47
MOT test number	919015763308
Result	✓ Passed

**MOT #21**

2022-12-05 11:17

MOT test number

966492366812

Result**✗ Failed**

- Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive Engine oil leak at gearbox area (8.4.1 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Disc scored (1.1.14 (a) (ii))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Service due light on
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre inner tread on 1.6mm 205 60 16 (5.2.3 (e))
- Advice** Nearside Front Brake calliper anti-rattle spring insecure and fouling wheel
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Headlamp aim not tested (4.1.2 (b))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened Discs worn and corroded (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** No coolant in expansion tank
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Tyre worn on edges and at 3mm 205 60 16 (5.2.3 (e))

**MOT #20**

2021-11-23 09:47

MOT test number

468294024265

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))

MOT #19

2021-11-02 11:09

MOT test number

465767472259

Result

✗ Failed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Inner Suspension arm pin or bush excessively worn possibly insecure retaining bolt (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Tyre obviously under inflated (5.2.3 (l))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

MOT #18

2020-11-30 13:45

MOT test number

487897908088

Result

✓ Passed

- Advice** Exhaust mounting defective rear exhaust box mounting (6.1.2 (a))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear axle mounting bushes split/ worn on nearside and offside
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #17**

2020-11-28 11:37

MOT test number

724319831329

Result**✗ Failed**

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear axle mounting bushes split/ worn on nearside and offside

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

Advice Exhaust mounting defective rear exhaust box mounting (6.1.2 (a))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #16

2019-05-28 15:07

MOT test number

997601338824

Result**✓ Passed**

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to legal limit/worn on edge also worn smooth on edges and cracking/perishing (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #15**

2019-05-27 14:10

MOT test number

322356852286

Result**✗ Failed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge also worn smooth on edges and cracking/perishing (5.2.3 (e))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #14

2018-05-25 11:08

MOT test number

570358050481

Result**✓ Passed****MOT #13**

2018-05-24 14:06

MOT test number

291846296382

Result**✗ Failed**

Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Rear Direction indicator incorrect colour both sides bulbs deteriorated (4.4.3 (a))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12

2017-05-26 16:27

MOT test number

586713826727

Result**✓ Passed**

**MOT #11** 2017-05-26 14:57**MOT test number** 677595912708**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #10** 2016-05-27 08:50**MOT test number** 137256973504**Result** ✓ Passed**Advice** Rear wiper blade split**MOT #9** 2015-05-29 16:15**MOT test number** 907739345115**Result** ✓ Passed**MOT #8** 2015-05-28 11:31**MOT test number** 665058245177**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear brake recording little or no effort (3.7.B.5a)**MOT #7** 2014-04-25 12:05**MOT test number** 249375514473**Result** ✓ Passed**MOT #6** 2013-02-11 11:36**MOT test number** 825572743070**Result** ✓ Passed**Advice** Offside Front Ball joint has slight play (2.2.B.1f)

**MOT #5** 2013-02-08 11:28**MOT test number** 458639933064**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Ball joint has slight play (2.2.B.1f)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #4** 2011-11-01 13:02**MOT test number** 439355201471**Result** ✓ Passed**Notice** Slight play in steering rack at offside**MOT #3** 2011-10-26 11:42**MOT test number** 757639491256**Result** ✗ Failed**Notice** Slight play in steering rack at offside**Fail** Offside Outer Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Fail** Nearside Rear rear brake binding (3.7.B.1)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #2** 2010-10-13 14:14**MOT test number** 584796480227**Result** ✓ Passed**Notice** Slight play in steering rack at offside



MOT #1	2010-10-11 12:24
MOT test number	463034880293
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Slight play in steering rack at offside
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-09-03
Last registration	2024-01-31
Complete history	See info



Registration #1	2007-09-03	22 mi
Registration #2	2010-10-11	30.290 mi
Registration #3	2010-10-13	30.380 mi
Registration #4	2011-10-26	42.913 mi
Registration #5	2011-11-01	42.913 mi
Registration #6	2013-02-08	56.352 mi
Registration #7	2013-02-11	56.387 mi
Registration #8	2014-04-25	67.615 mi
Registration #9	2015-05-28	75.757 mi
Registration #10	2015-05-29	75.760 mi
Registration #11	2016-05-27	78.092 mi
Registration #12	2017-05-26	79.343 mi
Registration #13	2017-05-26	79.343 mi
Registration #14	2018-05-26	80.594 mi
Registration #15	2019-05-26	81.845 mi
Registration #16	2020-05-26	83.096 mi
Registration #17	2021-05-26	84.347 mi
Registration #18	2022-05-26	85.598 mi
Registration #19	2023-05-26	86.849 mi
Registration #20	2024-01-31	88.100 mi
Registration #21	2024-01-31	88.100 mi
Registration #22	2024-01-31	88.100 mi
Registration #23	2024-01-31	88.100 mi
Registration #24	2024-01-31	88.100 mi
Registration #25	2024-01-31	88.100 mi



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

C000000