






report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT GTE ADVANCE DSG
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 100 km/h	7.6 seconds
0 - 60 mph	7.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	115 kW / 157 HP / 215 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.395 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	166.2 mpg
CO2 emission	40 g/km
CO2 label	A



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2022-09-15

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-09

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-28
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #6		2023-09-21 11:21
MOT test	number	538580129366
Result		✓ Passed
Next expi	ry date	2024-09-28
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2022-09-29 09:37
MOT test number	369504342860
Result	✓ Passed

MOT #4		2022-02-17 16:23
MOT test	number	452123193565
Result		✓ Passed
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



× Failed

MOT #3 2022-02-14 16:04

MOT test number 887988156949

Result

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #2 2021-02-19 14:37

MOT test number 172337336162

Result

Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2021-02-18 14:50

MOT test number 810063778523

Result × Failed

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/11



Tax & MOT check





Expires: 28 September 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	







Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	SIE UK
Plate since	
Current registration	NK SIE
Plate since	
	More info

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-01
Last registration	2023-09-21
Complete history	See info



Registration #1	2018-03-01	18 mi
Registration #2	2021-02-18	47.737 mi
Registration #3	2021-02-19	47.737 mi
Registration #4		11.777 es
Registration #5	2022-02-14	57.453 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 ea
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1660 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	pago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CUKC118668