





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	E E220 CDI SE
Colour	Black
Year of manufacture	2014
Top speed	141 mph
0 - 60 mph	8.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2025-03-24
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	32
Total items failed	0

MOT #15		2024-03-25 16:43
MOT test	number	429782992525
Result		✓ Passed
Next expi	ry date	2025-03-24
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #14		2023-03-20 14:35
MOT test	number	562074029575
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #13	2022-03-09 16:23
MOT test number	475325993948
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT #12 2021-03-10 19:00
MOT test number 968953939296

MOT test number 968953939296

Result

Passed

MOT #11 2020-12-09 18:04

MOT test number 242878901849

Result
✓ Passed

Advice STOP LAMP MALFUNCTION WARNING ON DASHBOARD

MOT #10 2020-12-07 20:38

MOT test number 932603871959

Result X Failed

MAJOR Front Brake disc significantly and obviously worn BOTH (1.1.14 (a) (i))

Advice STOP LAMP MALFUNCTION WARNING ON DASHBOARD

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MAJOR Rear Brake disc significantly and obviously worn BOTH (1.1.14 (a) (i))

MOT #9 2018-11-28 13:20

MOT test number 643621868675

Result

Passed

Advice Warning lamp on

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2018-05-30 10:56

MOT test number 872638638386

Result

Passed

Minor Rear Position lamp light intensity obviously reduced (4.2.3 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2018-05-14 10:48 932708657287 **MOT** test number Result ✓ Passed **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Rear Brake pad(s) wearing thin (3.5.1g) Advice Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)Advice SERVICE LAMP ON Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Front Brake pad(s) wearing thin (3.5.1g) **Advice**

MOT #6 2017-11-14 10:29 **MOT** test number 405478196732 Result ✓ Passed Rear Brake pad(s) wearing thin (3.5.1g) **Advice**

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2017-05-15 14:56 161226662875 **MOT** test number Result Passed **Advice** Offside Front Tyre has slight damage on sidewall.

MOT #4 2016-11-16 16:54 **MOT** test number 143337444706 Result Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2016-05-17 16:11 **MOT test number** 787308647677 Result ✓ Passed **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Brake performance could be better. **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2		2015-11-17 12:24
MOT test	number	590434208562
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Engine covers and tray fitted obscuring testable items from view of test.	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2015-05-21 10:27
MOT test number	286121545479
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How man MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Description of the premium report here.	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-07-15
Last registration	2024-03-25
Complete history	See info



Registration #1	2014-07-15	23 mi
Registration #2	2015-05-21	10.054 mi
Registration #3	2015-11-17	17.997 mi
Registration #4	2016-05-17	25.803 mi
Registration #5	2016-11-16	34.649 mi
Registration #6	2017-05-15	41.561 mi
Registration #7	2017-11-14	51.157 mi
Registration #8	2018-05-14	58.600 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
0567	
60569	
iew the complete MERCEDES-BENZ factory list for this	More info >

- C		_		
- I)ım	ension	SW	weiat	٦t
	ווטוכוום	3 UX	WEIGH	

Width	2071 mm
Height	1474 mm
Length	4879 mm
Wheel base	2874 mm
Kerb weight	1735 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	59 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	65192432365373

CarCheck.co.uk page 12/12