





report date: 2024-03-28

General information

Make	AUDI
Model	TT S3 QUATTRO
Colour	Black
Year of manufacture	2002
Top speed	151 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	221 BHP
Max. torque	280 Nm at 2.200 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	21.6 mpg
Consumption combined	39.8 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-12

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

MOT history

MOT expiry date	2023-06-29
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	48
Total items failed	21

MOT #21		2022-06-30 11:46
MOT test	number	467529684939
Result		✓ Passed
Next expi	ry date	2023-06-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view	v (3.2 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner ed	dge (5.2.3 (e))
Advice (5.3.4 (a)	Nearside Front Upper Macpherson strut pin or bush worn but not resulting (i))	in excessive movement
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1	.11 (c))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edg	ge (5.2.3 (e))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.	.1.11 (c))

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #20 2022-05-17 08:50
MOT test number 244678969322

Result × Failed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear

bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

MOT #19 2021-05-17 09:45

MOT test number 596964792487

Result

✓ Passed

MOT #18 2019-07-30 15:49

MOT test number 708524326151

Advice Nearside Rear Brake pipe corroded, covered in grease or other material x1 (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #17 2019-07-29 13:51

MOT test number 815477961941

Result X Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material x1 (1.1.11 (c))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice Offside Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))

MOT #16 2018-07-13 11:58

MOT test number 510464242152

Result
✓ Passed

Minor Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15 2017-07-26 14:06

MOT test number 492695085376

Result

Passed

MOT #14 2017-07-26 10:23

MOT test number 493073861331

Result X Failed

Fail Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

Offside Rear coil spring broken (2.4.C.1a)

Fail

Fail Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2016-01-05 12:16 **MOT** test number 314039937449 Result × Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Offside Front coil spring broken (2.4.C.1a) Battery insecure (1.9.1) Fail Fail Nearside Registration plate lamp not working (1.1.C.1d) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c) Fail Offside Headlamp aim too low (1.8)

MOT #11	2014-07-23 13:56
MOT test number	106714504273
Result	✓ Passed

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT #	10	2014-07-21 12:24
MOT te	est number	686432004225
Result		× Failed
Fail	Offside Front position lamp(s) not working (1.1.A.3b)	
Fail	Nearside Front coil spring fractured (2.4.C.1a)	
Fail	Nearside Front Macpherson strut has excessive movement at the upper attachment	(2.5.A.1c)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail	Offside Stop lamp not working (1.2.1b)	
Fail	Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Fail	Nearside Rear Braking system leaking (3.6.A.1)	

MOT #9	2013-07-12 11:50
MOT test number	189283293186
Result	✓ Passed
MOT #8	2012-07-21 11:17
MOT test number	535963702240
Result	✓ Passed
MOT #7	2011-07-11 12:35

MOT #7	2011-07-11 12:35
MOT test number	698342191188
Result	✓ Passed
Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	

MOT #6	2010-07-12 11:00
MOT test number	573493490109
Result	✓ Passed

CarCheck.co.uk page 7/16



MH02GKD report date: 2024-03-28

MOT #5 2009-07-16 13:23

MOT test number 324287799195

Result ✓ Passed

Advice Rear brake disc slightly pitted (3.5.1h)

Advice Offside Front Lower Windscreen has damage to an area less than a 10mm circle within zone 'A'

(8.3.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front brake disc slightly pitted (3.5.1h)

Advice Rear brake disc slightly scored (3.5.1h)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Anti-roll bar corroded but not seriously weakened (2.4.G.1)

Advice Front brake disc slightly scored (3.5.1h)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2008-07-11 10:46

MOT test number 814473498121

Result \rightarrow Passed

Advice Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

MOT #3 2008-07-11 10:46

MOT test number 850543498101

Result ★ Failed

Advice Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Pass with rectification Offside Front Headlamp aim too high (1.8)

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #2	2007-07-17 09:54
MOT test number	453648397142
Result	✓ Passed
Notice Front wipers not clearing screen effectively.	

MOT #1	2006-06-28 14:59
MOT test number	773189476192
Result	✓ Passed

CarCheck.co.uk page 9/16



report date: 2024-03-28

Tax & MOT check



X MOT

Tax expired: 1 April 2024 Expired: 29 June 2023

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	29 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>h</u>	
manage of the same	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-03-27
Last registration	2022-06-30
Complete history	See info



2002-03-27	21 mi
2006-06-28	45.062 mi
2007-07-17	53.217 mi
2008-07-11	61.081 mi
2009-07-16	69.258 mi
2010-07-12	77.098 mi
2011-07-11	84.680 mi
2012-07-21	92.281 mi
2013-07-12	101.085 mi
2014-07-21	109.009 mi
2014-07-23	109.015 mi
	11.777 es
	0.77 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	11,777 est
	11.777 es
	2006-06-28 2007-07-17 2008-07-11 2009-07-16 2010-07-12 2011-07-11 2012-07-21 2013-07-12 2014-07-23

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1415 mm
Length	4159 mm
Wheel base	2519 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number CarCheck.co.uk	BAM 037674 page 16/16